



LOC RWY 19
RICHLAND (RLD)

MISSED APPROACH: Climbing right turn to 4000 on heading 045° and on PSC VOR/ DME R-337 to BAKCA INT/I-RLD 13.7 DME and hold, continue climb-in-hold to 4000.

UNICOM
122.7 (CTAF) **L**

One Minute Holding Pattern



	0.3	1.1 NM	1.5 NM	2.4 NM	7.7 NM	
CATEGORY	A	B	C	D		
S-19	1300-1	910 (1000-1)	1300-2½	910 (1000-2½)		
 CIRCLING	1300-1¼	906 (1000-1¼)	1300-2¾ 906 (1000-2¾)	1940-3 1546 (1600-3)		
HOTUX FIX MINIMUMS (DUAL VOR RECEIVERS OR DME REQUIRED)						
S-19	880-¾	490 (500-¾)	880-1⅞	490 (500-1⅞)		
 CIRCLING	920-1 526 (600-1)	1000-1 606 (700-1)	1200-2¼ 806 (900-2¼)	1940-3 1546 (1600-3)		