

## FISHERS ISLAND

**ELIZABETH FLD** (ØB8) 8 SE UTC-5(-4DT) N41°15.13' W72°01.90'

NEW YORK  
L-33C, 34I  
IAP

7 NOTAM FILE BDR

**RWY 12-30:** H2345X100 (ASPH) MIRL

**RWY 12:** REIL. PAPI(P2L)—GA 3.0° TCH 20'. Road.

**RWY 30:** REIL. PAPI(P2R)—GA 3.0° TCH 20'.

**RWY 07-25:** H1806X75 (ASPH) MIRL

**RWY 07:** REIL. PAPI(P2L)—GA 3.75° TCH 20'. Ground.

**RWY 25:** REIL. PAPI(P2L)—GA 3.0° TCH 20'. Road.

**SERVICE:** LGT ACTIVATE MIRL Rwy 07-25 and 12-30, PAPI Rwy 07, Rwy 12, Rwy 25 and Rwy 30, REIL Rwy 07, Rwy 12, Rwy 25 and Rwy 30—CTAF.

**AIRPORT REMARKS:** Attended May-Oct Mon-Sat 1300-2130Z†, Sun 1500-2130Z†. Unattended 1 Nov-30 Apr. Arpt located 7.0 NM SE of New London CT. Ldg fee.

**AIRPORT MANAGER:** 917-675-0296

**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓡ **PROVIDENCE APP/DEP CON** 125.75 (Sun-Fri 1030-0530Z†, Sat

1030-0500Z†) other times ctc

**BOSTON CENTER APP/DEP CON** 124.85

**CLEARANCE DELIVERY PHONE:** For CD ctc Providence Apch at 401-738-8945, when Apch clsd ctc Boston ARTCC at 603-879-6859.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE GON.


**GROTON (T) VOR/DME** 110.85 GON Chan 45(Y) N41°19.82' W72°03.12' 183° 4.8 NM to fld. 9/14W.

VOR portion unusable:

241°-265° blo 5,000'

DME unusable:

355°-019° blo 3,000'



**FLOYD BENNETT MEML** (See GLENS FALLS on page 206)

## FORT ANN

**HARRIS** (83K) 2 W UTC-5(-4DT) N43°24.59' W73°31.96'

NEW YORK

261 NOTAM FILE BTV

**RWY 04-22:** 2200X50 (TURF) 1.7% up SW

**RWY 04:** Tree. Rgt tfc.

**RWY 22:** Tree.

**AIRPORT REMARKS:** Unattended. No flying west of rwy over houses. Upslope at thld Rwy 22.

**AIRPORT MANAGER:** 518-361-1380

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Albany Apch at 518-862-2299.

**FRANCIS S GABRESKI** (See WESTHAMPTON BEACH on page 253)

**FRANKFORT-HIGHLAND** (See UTICA/FRANKFORT on page 250)

**FREDERICK DOUGLASS/GREATER ROCHESTER INTL** (See ROCHESTER on page 239)

**FREEHOLD** (115) 1 NW UTC-5(-4DT) N42°21.84' W74°03.90'

NEW YORK

440 NOTAM FILE BTV

**RWY 12-30:** H2275X22 (ASPH) 0.7% up NW

**RWY 12:** Trees.

**RWY 30:** Trees.

**AIRPORT REMARKS:** Attended Apr-Dec 1400Z†-dusk. Extensive glider activity, especially on weekends. Rwy 12-30 sfc broken and spalling for entire length. Ctc arpt manager for fld conditions Dec 1-Apr 1, 518-966-8503. Rgt tfc for gliders Rwy 12 only. Rwy 12-30 100' by 2640' turf rwy adjacent to paved rwy (south edge) beginning at 735' from Rwy 30 thld.

**AIRPORT MANAGER:** 518-966-8503

**COMMUNICATIONS:** CTAF 122.85

**CLEARANCE DELIVERY PHONE:** For CD ctc Albany Apch at 518-862-2299.

**FRIKK** N40°46.59' W73°28.95' NOTAM FILE FRG.

**NDB (LOMW)** 407 FR 146° 4.2 NM to Republic. 153/14W.