

CRESCO**ROCKY HILL** (48P) 1 SE UTC-5(-4DT) N41°08.91' W75°16.52'

NEW YORK

1240 NOTAM FILE IPT

RWY 09-27: 1000X100 (TURF)

RWY 09: Thld dispclcd 130'. Trees.

RWY 27: Thld dispclcd 80'. Trees.

AIRPORT REMARKS: Unattended. Deer and wildlife on and invof arpt. Announce tfc on—CTAF 122.9.

AIRPORT MANAGER: 570-595-2269

COMMUNICATIONS: CTAf 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Allentown Apch at 800-728-6322.

DANVILLE (8N8) 3 SW UTC-5(-4DT) N40°56.90' W76°38.64'

NEW YORK

L-30J

IAP

559 B NOTAM FILE IPT

RWY 09-27: H3000X60 (ASPH) MIRL 0.4% up E

RWY 09: Trees.

RWY 27: Trees.

SERVICE: S4 LGT Lighting NSTD. ACTVT MIRL Rwy 09-27 drg periods of darkness only—CTAF. Rwy 27 thld lghts dispclcd 365' from rwy end for ngt displacement. Rwy end lgtd with two red lghts on left side (NSTD).

AIRPORT REMARKS: Attended irregularly. After hrs ctc 570-274-6190. Deer and wildlife on and invof arpt. Radio controlled airplane ops N of rwy. Main ramp no prop wash invof main hangar due to acft painting.

AIRPORT MANAGER: 570-274-6190

COMMUNICATIONS: CTAf/UNICOM 122.8

® WILKES-BARRE APP/DEP CON 126.3


CLEARANCE DELIVERY PHONE: For CD ctc Wilkes-Barre Apch at

570-655-2084.

RADIO AIDS TO NAVIGATION: NOTAM FILE IPT.

MILTON (L) VORTACW 109.2 MIP Chan 29 N41°01.40'

W76°39.92' 177° 4.6 NM to fld. 1000/9W.

**DECK** (See MYERSTOWN on page 292)**DONEGAL SPRINGS AIRPARK** (See MOUNT JOY/MARIETTA on page 290)**DOVER****LAZY B RANCH** (0P8) 3 E UTC-5(-4DT) N40°01.47' W76°48.92'

NEW YORK

476 NOTAM FILE IPT

RWY 05-23: H2400X60 (ASPH-CONC) LIRL 1.3% up SW

RWY 05: Brush.

RWY 23: Brush.

SERVICE: LGT For LIRL Rwy 05-23 key 122.9 five times.

AIRPORT REMARKS: Unattended. Ctc arpt manager 717-292-7029. Deer invof arpt. Turf area parallel to Rwy 05-23, for taxi only, marked with yellow cones.

AIRPORT MANAGER: 717-891-7639

COMMUNICATIONS: CTAf 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Harrisburg Apch at 800-932-0712.