

## NANDR TWO DEPARTURE



## DEPARTURE ROUTE DESCRIPTION

TAKEOF OFF RUNWAY 16L: Climb on heading 166° or as assigned by ATC, thence . . . .

TAKEOF OFF RUNWAY 16R: Climb on heading 166° to 1100 before turning right or as assigned by ATC, thence . . . .

TAKEOF OFF RUNWAYS 34L/R: Climb on heading 346° or as assigned by ATC, thence . . . .

. . . . expect RADAR vectors to cross CUZNO at or above 3000, then on track 357° to cross NANDR at or below 13000, then on assigned transition.

EAKER TRANSITION (NANDR2.EAKER)

MC ALESTER TRANSITION (NANDR2.MLC)

OKMULGEE TRANSITION (NANDR2.OKM)

ROLLS TRANSITION (NANDR2.ROLLS)

TULSA TRANSITION (NANDR2.TUL)

WILL ROGERS TRANSITION (NANDR2.IRW)

ZEMMA TRANSITION (NANDR2.ZEMMA)