

POST MILLS (2B9) O E UTC-5(-4DT) N43°53.02' W72°15.13'

NEW YORK

696 NOTAM FILE BTW

RWY 04-22: 2900X80 (TURF)**RWY 04:** Trees. Rgt tfc.**RWY 22:** Road.**RWY 05-23:** 2300X80 (TURF) 0.8% up NE**RWY 05:** Trees. Rgt tfc.**RWY 23:** Road.**SERVICE:** S2

AIRPORT REMARKS: Attended irregularly. Ultralights; gliders and hot air balloons on and invof arpt. Trees 200' from end of Rwy 22 and 23. 60' trees directly adjacent to runway edge, left. Uniform width and length of Runways 05-23 is 2,200' 80'. Non-std turf cones placement—do not use delineate actual thlds—all rwy. Acft ops counts unavailable. No snow removal. Arpt open to ski acft only when snow covered. Call 802-333-9254 for info. Propane avbl for hot air balloons.

AIRPORT MANAGER: 802-333-9254**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.**RUTLAND/SOUTHERN VERMONT RGNL** (RUT)(KRUT) 5 S UTC-5(-4DT) N43°31.78'

NEW YORK

W72°56.98'

H-11D, 12K, L-32G

787 B Class IV, ARFF Index A NOTAM FILE RUT

IAP

RWY 01-19: H5304X100 (ASPH-GRVD) S-40, D-68, 2S-86

PCN 30 F/D/X/U MIRL

RWY 01: PVASI(PSIR)—GA 3.5° TCH 17'. Thld dspcd 300'. Hill.**RWY 19:** MALSR. PAPI(P4L)—GA 3.2° TCH 55'. Rgt tfc.**RWY 13-31:** H3169X75 (ASPH) S-30 PCN 5 F/D/X/U MIRL**RWY 13:** REIL. Road.**RWY 31:** Trees.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 01:** TORA-5303 TODA-5303 ASDA-5303 LDA-5003**RWY 19:** TORA-5003 TODA-5003 ASDA-5003 LDA-5003

SERVICE: S4 **FUEL** 100LL, JET A **LGT** ACTVT MALSR Rwy 19; REIL Rwy 13; MIRL Rwy 01-19 and 13-31—CTAF. Rwy end 01: VGSI OTS UFN.

NOISE: Noise sensitive area SE of arpt ctc amgr.

AIRPORT REMARKS: Attended 1200-0100Z±. Birds on and invof arpt. For aft hrs svc call 802-773-3348. Rwy conditions may not be monitored or reported when the arpt is unattended. Rwy 13-31 not avbl for skedd acf ops (ldgs and tkof) more than 9 pax seats or unskd acf ops at least 31 pax seats. Avbl for acf ops taxi only. Clsd to unskd acf ops with more than 9 pax seats exc 48 hr PPR, call amgr 802-786-8881. Use Twy A to taxi to or from AER 01 or 19. Twy C connects main aprn with Twy A. Acft with wing spans exceeding 79 ft auzd to use Twy H & Twy B east of Rwy 01-19 & Rwy 13-31 for tax & Rwy 01 & 19 for tkof & ldg. Type I and type IV deicing avbl. Cold temperature airport. Altitude correction required at or below -8C. Ldg fees may apply for coml acft.

AIRPORT MANAGER: 802-585-5586**WEATHER DATA SOURCES:** AWOS-3PT 118.375 (802) 747-3044.**COMMUNICATIONS:** CTAF/UNICOM 122.8

RCO 122.3 (BURLINGTON RADIO)

② **BOSTON CENTER APP/DEP CON** 135.7**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.**RADIO AIDS TO NAVIGATION:** NOTAM FILE RUT.**SMUTO NDB (MHW)** 221 DY0 N43°42.37' W72°57.40' 193° 10.6 NM to fld. 1138/15W.

NDB unusable:

351°-189° byd 15 NM

ILS/DME 111.7 I-RUT Chan 54 Rwy 19. Class IA. Glideslope unusable byd 4.00° right of course.