

CONTINUED FROM PRECEDING PAGE

RADIO AIDS TO NAVIGATION: NOTAM FILE AUG.

(VL) (DH) VOR/DME 114.95 AUG Chan 96(Y) N44°19.20' W69°47.79' at fld. 349/18W.

VOR unusable:

- 005°-015° byd 10 NM blo 7,000'
- 018°-050° byd 40 NM
- 055°-058° byd 40 NM
- 065°-089° byd 40 NM
- 075°-089° byd 25 NM blo 3,000'
- 090°-115° byd 15 NM
- 116°-175° byd 40 NM
- 116°-189° byd 25 NM blo 3,000'
- 188°-207° byd 40 NM
- 190°-205° byd 10 NM blo 5,000'
- 206°-220° byd 25 NM blo 3,000'
- 208°-213° byd 40 NM blo 3,000'
- 208°-213° byd 49 NM blo 7,000'
- 208°-213° byd 68 NM
- 225°-245° byd 40 NM
- 246°-256° byd 40 NM blo 7,000'
- 246°-256° byd 53 NM
- 257°-261° byd 40 NM
- 271°-275° byd 40 NM
- 300°-353° byd 40 NM

DME unusable:

- 010°-070° byd 25 NM blo 7,000'
- 071°-143° byd 25 NM blo 3,000'
- 144°-154° byd 25 NM blo 7,000'
- 155°-189° byd 25 NM blo 3,000'
- 190°-205° byd 10 NM blo 5,000'
- 206°-220° byd 25 NM blo 3,000'
- 221°-285° byd 15 NM blo 6,000'

DUNNS NDB (LOMW) 366 AU N44°24.66' W69°51.64' 171° 6.1 NM to fld. 238/18W.

ILS 108.7 I-AUG Rwy 17. Class I.B. LOM DUNNS NDB. Glideslope unusable byd 5° right side of LOC course; blw 430'; byd 9 NM. LOC unusable fm 0.5 NM to thld abv 1,500'.

BANGOR

BANGOR INTL (BGR)(KBGR) P (ANG ARNG) 3 W UTC-5(-4DT) N44°48.45' W68°49.69'
 192 B TPA—See Remarks LRA ARFF Index—See Remarks NOTAM FILE BGR

HALIFAX
 H-11D, L-32I
 IAP, DIAP, AD

RWY 15-33: H11440X200 (ASPH-GRVD) S-100, D-210, 2D-400
 PCN 120R/A/W/T HIRL CL

RWY 15: ALSF2. TDZL. PAPI(P4L)—GA 3.0° TCH 55'. RVR-TMR 0.4% down.

RWY 33: MALSR. PAPI(P4L)—GA 3.0° TCH 57'. RVR-TMR Trees.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 15: TORA-11440 TODA-11440 ASDA-11440 LDA-11440

RWY 33: TORA-11440 TODA-11440 ASDA-11440 LDA-11440


SERVICE: S4 FUEL 100LL, JET A OX 2, 4 MILITARY—JASU 1(MD-3) 1(MC-11) (MA-1A) FUEL A+ + (Mil), A, A+ (C207-992-4600) (NC-100LL) FLUID SP PRESAIR LPOX LOX -Off-base contracted LOX avbl H24-rqr 24 hr notice. OIL O-133-148(Mil)

AIRPORT REMARKS: Attended continuously. TPA for turbo jet acct is 2000(1808) unless otherwise instructed. ARFF Index B with Index E capabilities avbl 24/7. Flight Notification Service (ADCUS) available. Twy L CLOSED.

MILITARY REMARKS: Transient acct may be diverted to civilian side during non-duty hrs & weekends. Fee required; no ANG transient alert.

CAUTION Bash Phase II period Sep-Nov, Apr-May. Expect increased bird activity. Ctc Base Ops/Command Post/SOF for current bird watching cond. **MISC** Rwy 15-33 grooved. **ANG** Opr 1100-1930Z‡ Mon-Fri, clsd weekends and hol. PPR rqr for ANG ramp. Ctc fld mgmt DSN 698-7232, C207-404-7232 for PPR dur opr hrs. Pre-coord all transportation requirements and and haz cargo with PPR rqr. PPR valid +/- 1 hr unless prior coord. 3 hr out call, 30 min out call 311.0 to CFM customs/AG and tran svc. Comd post C207-404-7788 24 hrs. **ARNG** Opr 1230-2100Z‡ Mon-Fri exc hol. Ltd maint. J8. PPR May-Oct svc DSN 626-1100.

AIRPORT MANAGER: 207-992-4600



CONTINUED ON NEXT PAGE

