

GROVETON—TRINITY CO (33R) 3 NW UTC-6(-5DT) N31°05.06' W95°09.85'

340 B NOTAM FILE CXO

RWY 16-34: H3500X60 (ASPH) S-8 LIRL

RWY 16: Trees.

RWY 34: Trees.

SERVICE: LGT ACTIVATE LIRL Rwy 16-34—CTAF.

AIRPORT REMARKS: Unattended. Deer and feral hogs on and invof arpt.

AIRPORT MANAGER: 936-642-1746

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.

RADIO AIDS TO NAVIGATION: NOTAM FILE LFK.

LUFKIN (VH) (H) VORTACW 112.1 LFK Chan 58 N31°09.75' W94°43.01' 254° 23.5 NM to fld. 207/5E.

TACAN AZIMUTH unusable:

260°-275° byd 30 NM

275°-260° byd 30 NM blo 2,500'

DME unusable:

260°-275° byd 30 NM

275°-260° byd 30 NM blo 2,500'

VOR unusable:

305°-312° byd 40 NM

313°-323° byd 40 NM blo 2,300'

313°-323° byd 66 NM

324°-330° byd 40 NM

HOUSTON

L-19E, 21A

GRUVER MUNI (E19) 2 SW UTC-6(-5DT) N36°14.02' W101°25.93'

3205 B NOTAM FILE FTW

RWY 02-20: H4698X60 (ASPH) S-12.5 MIRL 0.4% up SW

RWY 02: Fence.

RWY 20: Fence.

SERVICE: LGT Actvt MIRL Rwy 02-20—CTAF.

AIRPORT REMARKS: Unattended. Extsv pavement cracking, potholes at Rwy 20 thr.

AIRPORT MANAGER: 806-733-2424

COMMUNICATIONS: CTAF 122.9

③ ALBUQUERQUE CENTER APP/DEP CON 127.85

CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.

RADIO AIDS TO NAVIGATION: NOTAM FILE BGD.

BORGER (L) TACAN Chan 23 BGD (108.6) N35°48.42' W101°22.93' 344° 25.7 NM to fld. 3130/11E.

TACAN AZIMUTH unusable:

220°-320° byd 10 NM blo 12,000'

WICHITA

L-15B

IAP

GUADALUPE PASS N31°49.97' W104°48.55'

RCO 122.5 (ALBUQUERQUE RADIO)

EL PASO

L-6G

GUTHRIE N33°46.70' W100°20.17' NOTAM FILE FTW.

(L) DME 114.5 GTH Chan 92 010° 15.2 NM to Dan E Richards Muni. 1941.

DALLAS—FT. WORTH

H-6G, L-17B

H H COFFIELD RGNL (See ROCKDALE on page 401)

HALE CO (See PLAINVIEW on page 392)

HALL—MILLER MUNI (See ATLANTA on page 247)

HALLETTSVILLE MUNI (34R) 3 S UTC-6(-5DT) N29°23.40' W96°57.36'

278 B NOTAM FILE CXO

RWY 17-35: H3210X60 (ASPH) S-7 MIRL

RWY 17: Trees.

RWY 35: Trees.

SERVICE: FUEL 100LL LGT MIRL Rwy 17-35 preset low intst; to incr intst ACTVT—CTAF.

AIRPORT REMARKS: Unattended. 100LL 24 hr self serve. Rwy 17 and Rwy 35 rwy mkgs discolored.

AIRPORT MANAGER: 361-798-2201

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.

RADIO AIDS TO NAVIGATION: NOTAM FILE VCT.

VICTORIA (L) (L) VORW/DME 109.0 VCT Chan 27 N28°54.02' W96°58.74' 356° 29.3 NM to fld. 125/6E.

VOR unusable:

345°-355° byd 30.0 NM

HOUSTON

L-19E, 21A