

PAMPA

PERRY LEFORS FLD (PPA)(KPPA) 5 NW UTC-6(-5DT) N35°36.78' W100°59.78'

DALLAS-FT WORTH
H-6G, L-15B
IAP

3245 B NOTAM FILE PPA
RWY 17-35: H5862X100 (ASPH) S-16 MIRL
RWY 17: PAPI(P2L)—GA 3.0° TCH 45'. Road.
RWY 35: PAPI(P2L)—GA 3.0° TCH 45'.
RWY 05-23: H4500X75 (ASPH) S-17 MIRL
RWY 23: P-line.

SERVICE: S4 FUEL 100LL, JET A1+ LGT Dusk-Dawn. MIRL Rwy 05-23 and 17-35 preset low inst; to incr inst actv—CTAF.

AIRPORT REMARKS: Attended 1300-0100Z± hours. Antelope on and inwof rws. For fuel after hours call 806-395-1117, 806-662-8209. No line of sight btn both rwy ends.

AIRPORT MANAGER: (806) 669-8007

WEATHER DATA SOURCES: AWOS-3 118.725 (806) 669-1333.

COMMUNICATIONS: CTAF/UNICOM 122.7


Ⓡ **ALBUQUERQUE CENTER APP/DEP CON** 127.85

CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.

RADIO AIDS TO NAVIGATION: NOTAM FILE BGD.

BORGER (L) TACAN Chan 23 BGD (108.6) N35°48.42' W101°22.93' 111° 22.2 NM to fld. 3130/11E.

TACAN AZIMUTH unusable:
220°-320° byd 10 NM blo 12,000'



PANDE N35°08.79' W101°48.33' NOTAM FILE AMA.

DALLAS-FT WORTH
L-15B

NDB (LOWW) 251 AM 040° 6.6 NM to Rick Husband Amarillo Intl. 3609/8E. NDB unmonitored when ATCT clsd.

PANHANDLE-CARSON CO (T45) 1 NE UTC-6(-5DT) N35°21.70' W101°21.91'

DALLAS-FT WORTH
L-15B
IAP

3454 B NOTAM FILE FTW
RWY 17-35: H4404X60 (ASPH) S-12.5 MIRL
RWY 17: Road.
RWY 35: Road. Rgt tfc.

SERVICE: FUEL 100LL LGT MIRL Rwy 17-35 preset low ints, to increase ints ACTIVATE-123.5.

AIRPORT REMARKS: Unattended.

AIRPORT MANAGER: 806-537-3517

COMMUNICATIONS: CTAF/UNICOM 122.7


Ⓡ **AMARILLO APP/DEP CON** 119.5 (1200-0600Z±)

Ⓡ **ALBUQUERQUE CENTER APP/DEP CON** 127.85 (0600-1200Z±)

CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.

RADIO AIDS TO NAVIGATION: NOTAM FILE FTW.

(H) (H) **VORTACW** 116.6 PNH Chan 113 N35°14.10' W101°41.94' 057° 18.1 NM to fld. 3595/8E.



PANHANDLE N35°14.10' W101°41.94' NOTAM FILE FTW.

DALLAS-FT WORTH
H-6G, L-15B

(H) (H) **VORTACW** 116.6 PNH Chan 113 at Rick Husband Amarillo Intl. 3595/8E.

PANOLA CO-SHARPE FLD (See CARTHAGE on page 267)