

**HENDERSONVILLE** (ØA7) 2 E UTC-5(-4DT) N35°18.46' W82°25.99'

ATLANTA

2084 NOTAM FILE RDU

L-25C

**RWY 15-33:** H3075X40 (ASPH) S-10 RWY LGTS(NSTD)**RWY 15:** Thld dsplcd 270'. Trees.**RWY 33:** Thld dsplcd 325'. Trees.**SERVICE:** S4 **LGT** Actvt LIRL Rwy 15-33—CTAF. OTS indefly. Rwy 15-33 no end or dsplcd thld lgts; lgts 50' from rwy edge south side and 11' from rwy edge north side. OTS indefly daylight opr only.**AIRPORT REMARKS:** Attended 1330-2230Z†. For svc after hrs call 828-693-1897. Acft parked 40' from edge of Rwy 33. Numerous obstructions in apch and primary sfcs. Hangar 90' left of Rwy 33. Landing traffic use caution when winds greater than 10 kts. Rwy 15 numbers and rwy markings smaller than standard. Numbers visible but cntrln nonexistent. North side of rwy has 60' trees 80' from cntrln.**AIRPORT MANAGER:** 828-693-1897**COMMUNICATIONS:** CTAF/UNICOM 123.0**CLEARANCE DELIVERY PHONE:** For CD ctc Asheville Apch at 828-684-7259. When Asheville Apch clsd, for CD ctc Atlanta ARTCC at 770-210-7692.**RADIO AIDS TO NAVIGATION:** NOTAM FILE RDU.**SUGARLOAF MOUNTAIN (L) (L) VORTACW** 112.2 **SUG** Chan 59 N35°24.39' W82°16.12' 236° 10.0 NM to fld. 3970/2W.**HIATT** (See THOMASVILLE on page 347)**HICKORY****HICKORY RGNL** (HKY)(KHKY) 3 W UTC-5(-4DT) N35°44.47' W81°23.37'

CHARLOTTE

1190 B Class I, ARFF Index A NOTAM FILE HKY MON Airport

H-9B, 12H, L-25D

**RWY 06-24:** H6401X150 (ASPH-GRVD) S-120, D-198, 2D-321,

2D/2D2-766 PCN 56 F/C/W/T HIRL 0.8% up NE

**RWY 06:** REIL. PAPI(P4L)—GA 3.0° TCH 57'. Trees.**RWY 24:** MALSR. PAPI(P4L)—GA 3.0° TCH 54'.**RWY 01-19:** H4400X150 (ASPH) S-78, D-104 PCN 30 F/C/X/T

MIRL 0.6% up N

**RWY 01:** REIL. PAPI(P4L)—GA 3.0° TCH 42'. Tree.**RWY 19:** REIL. VASI(V4R)—GA 3.0° TCH 33'.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 06:** TORA-6401 TODA-6401 ASDA-6401 LDA-6401**RWY 24:** TORA-6401 TODA-6401 ASDA-6401 LDA-6401**SERVICE:** S4 **FUEL** 100LL, JET A **ØX** 1, 2 **LGT** Dusk-Dawn. ACTVT MALSR Rwy 24; REIL Rwy 01; PAPI Rwy 06 and 24; HIRL Rwy 06-24; MIRL Rwy 01-19—CTAF (0400-1200Z†). Rwy 19 VASI unusbl byd 5° rgt of crs.**AIRPORT REMARKS:** Attended Mon-Fri 1200-0000Z†, Sat-Sun 1200-0000Z†. Svcs avbl Mon-Fri 0700-2100 lcl, Sat and Sun 0700-1900 lcl, after hrs svcs call 828-514-5638. 100LL avbl after hrs with credit card. Tkfs Rwy 19 prohibited when twr clsd. No line of sight btn Rwy 19 and Rwy 24. Rwy 01-19 not avbl for scheduled acr opns with more than 9 psgr seats or unscheduled acr at least 31 psgr seats. Clsd to unscheduled air carrier ops with more than 30 pax seats exc 24 hr PPR call arpt mgr 828-323-7408. Rwy 01-19 moderate transverse and longitudinal cracking; vegetation present in cracking. Rwy 06-24 markings badly faded. Twy B at AER 19 not vsb from the twr. Rwy 06-24 mkgds badly faded.**AIRPORT MANAGER:** 828-323-7408**WEATHER DATA SOURCES:** ASOS 118.325 (828) 322-2996.**COMMUNICATIONS:** CTAF 128.15

Ⓡ ATLANTA CENTER APP/DEP CON 125.15

**TOWER** 128.15 (1200-0200Z†)**GND CON** 121.7 **CLNC DEL** 121.7 **CLNC DEL** 124.25 (when twr clsd)**AIRSPACE:** CLASS D svc 1200-0200Z†; other times CLASS E.**VOR TEST FACILITY (VOT)** 110.0**RADIO AIDS TO NAVIGATION:** NOTAM FILE RDU.**BARRETS MOUNTAIN (H) (H) VOR/DME** 113.75 **BZM** Chan 84(Y) N35°52.13' W81°14.43' 230° 10.6 NM to fld. 1880/6W.

VOR unusable:

030°-040° byd 15NM blo 8,500'

**TAWBA NDB (MHW/LOM)** 332 **HK** N35°47.19' W81°18.32' 243° 4.9 NM to fld. 986/6W. NOTAM FILE HKY.**ILS** 108.7 I-HKY Rwy 24. Class OF IE. LOM TAWBA NDB. Unmonitored when ATCT is clsd