

BARTLESVILLE MUNI (BVO)(KBVO) 2 NW UTC-6(-5DT) N36°45.80' W96°00.67'**KANSAS CITY**

717 B NOTAM FILE BVO

H-61, L-15E

RWY 17-35: H6850X100 (CONC-GRVD) S-50, D-100, 2S-127,
2D-170 MIRL 0.4% up S

IAP

RWY 17: MALSR. PAPI(P4L)—GA 3.0° TCH 53'. Trees. Rgt tfc.

RWY 35: REIL. PAPI(P4L)—GA 3.0° TCH 45'. Thld dspcd 649'.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 17: TORA-6201 TODA-6201 ASDA-6201 LDA-6201

RWY 35: TORA-6850 TODA-6850 ASDA-6850 LDA-6201

SERVICE: S4 FUEL 100LL, JET A+ QX4 LGT ACTVT MALSR Rwy 17;

REIL Rwy 35; PAPI Rwy 17 and Rwy 35—CTAF. MIRL Rwy 17-35

oper SS to SR and preset low instst, incr instst—CTAF.


AIRPORT REMARKS: Attended Mon-Thu 1300-0100Z†, Fri-Sun
1300-0000Z†.**AIRPORT MANAGER:** (918) 661-3500**WEATHER DATA SOURCES:** ASOS 132.675 (918) 336-2070.**COMMUNICATIONS:** CTAF 122.825

RCO 122.4 (MC ALESTER RADIO)

Ⓡ **KANSAS CITY CENTER APP/DEP CON** 128.6**BARTLESVILLE ADVISORY** 122.825 (Monitored Mon-Fri during business
hrs)**CLEARANCE DELIVERY PHONE:** For CD if una to ctc on FSS freq, ctc Kansas City
ARTCC at 913-254-8508.**AIRSPACE:** CLASS E svc Mon-Thu 1300-0100Z†, Fri 1300-2300Z†; other times CLASS G.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BVO.

(L) (L) VORW/DME 117.9 BVO Chan 126 N36°50.06' W96°01.11' 167° 4.3 NM to fld. 930/8E.

LOC 111.3 I-BVO Rwy 17. LOC unusable byd 20° right of course. LOC unmonitored.

**BEAVER MUNI** (K44) 1 SW UTC-6(-5DT) N36°47.88' W100°31.61'**WICHITA**

2491 B NOTAM FILE MLC

L-15C

RWY 17-35: H4050X60 (ASPH) S-4 MIRL

RWY 17: REIL. P-line.

RWY 35: REIL. Trees.

RWY 04-22: 2000X130 (TURF) 1.5% up SW

RWY 04: Road.

SERVICE: LGT ACTIVATE MIRL Rwy 17-35, REIL Rwy 17 and Rwy 35—CTAF.**AIRPORT REMARKS:** Unattended.**AIRPORT MANAGER:** 580-625-3331**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at 913-254-8508.**BLACKWELL-TONKAWA MUNI** (BKN)(KBKN) 5 SW UTC-6(-5DT) N36°44.71' W97°20.98'**WICHITA**

1030 B NOTAM FILE MLC

L-15D

RWY 17-35: H3501X60 (ASPH) S-30, D-48, 2D-98 MIRL

IAP

0.6% up N

RWY 17: PAPI(P2L)—GA 3.0° TCH 40'.

RWY 35: PAPI(P2L)—GA 3.0° TCH 40'.

SERVICE: FUEL 100LL LGT Actvt and incr MIRL Rwy 17-35—CTAF.

PAPI Rwy 17 and 35 opr consly.

AIRPORT REMARKS: Attended irregularly. Fuel avbl 24 hrs thru automated
credit card system.**AIRPORT MANAGER:** 580-363-4242**WEATHER DATA SOURCES:** AWOS-3PT 120.575 (580) 363-0688.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **KANSAS CITY CENTER APP/DEP CON** 127.8**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at
913-254-8508.**RADIO AIDS TO NAVIGATION:** NOTAM FILE PNC.**PIONEER (VH) (H) VORTACW** 113.2 PER Chan 79 N36°44.79'

W97°09.61' 264° 9.1 NM to fld. 1054/6E.

TACAN AZIMUTH unusable:

184°-194° blo 3,000'

