

FLABOB (See RIVERSIDE(RUBIDOUX) on page 250)

FORT BIDWELL (A28) 1 N UTC-8(-7DT) N41°52.59' W120°08.80'

KLAMATH FALLS

4616 TPA-5416(800) NOTAM FILE RNO
RWY 16-34: 3660X50 (GRVL-DIRT) 1.1% up N

RWY 16: Road.

AIRPORT REMARKS: Unattended. No snow removal. Rwy not regularly maintained, gravel and rocks up to 4 inch diameter on rwy. +4' fence, 75' east of rwy centerline for entire length of rwy.

AIRPORT MANAGER: (530) 233-4612

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

FORT JONES

SCOTT VALLEY (A30) 3 S UTC-8(-7DT) N41°33.47' W122°51.30'

KLAMATH FALLS

2728 B TPA-3528(800) NOTAM FILE RIU

L-21

RWY 16-34: H3700X50 (ASPH) S-12 MIRL

RWY 16: Tree. Rgt tfc.

RWY 34: Thld dspcd 200'.

SERVICE: FUEL 100LL LGT ACTIVATE MIRL Rwy 16-34-CTAF.

AIRPORT REMARKS: Unattended. US Forest Svc fire activity May thru Sep.

AIRPORT MANAGER: 530-842-8297

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE RIU.

FORT JONES (H) (H) VORW/DME 116.25 FJS Chan 109(Y)

N41°26.98' W122°48.39' 322° 6.8 NM to fld. 4900/19E.

VOR unusable:

018°-025° byd 22 NM blo 14,000'

074°-117° byd 33 NM

128°-146° byd 33 NM

147°-292° byd 11 NM

DME unusable:


018°-025° byd 22 NM blo 14,000'

074°-117° byd 33 NM

128°-146° byd 33 NM

147°-292° byd 11 NM

COMM/NAV/WEATHER REMARKS: Unicom ops not continuous, located in pilot lounge.



FORT JONES N41°26.98' W122°48.39' NOTAM FILE RIU.

KLAMATH FALLS

(H) (H) VORW/DME 116.25 FJS Chan 109(Y) 322° 6.8 NM to Scott Valley. 4900/19E.

L-21

VOR unusable:

018°-025° byd 22 NM blo 14,000'

074°-117° byd 33 NM

128°-146° byd 33 NM

147°-292° byd 11 NM

DME unusable:

018°-025° byd 22 NM blo 14,000'

074°-117° byd 33 NM

128°-146° byd 33 NM

147°-292° byd 11 NM

RCO 122.2 (RANCHO MURIETA RADIO)