


23334

ILS RWY 27L (SA CAT I)
HARTSFIELD-JACKSON ATLANTA INTL (ATL)


MISSED APPROACH: Climb to 1500 then climbing left turn to 4000 on heading 265° and RMG VORTAC R-165 to DUTIE/RMG 31.3 DME/RADAR and hold.



CLNC DEL 118.1	CPDLC
-----------------------------	-------



1500 ↑	4000 hdg 265°	RMG R-165	DUTIE RMG 31.3		VGSI and ILS glidepath not coincident (VGSI Angle 3.00/TCH 79).		SLVAA I-FSQ [22.5] RADAR
			ROMMM I-FSQ [19.1] RADAR		SEJAY RADAR		
			DEPOT I-FSQ [7.2] RADAR		GRMPI I-FSQ [11.9] RADAR		
			IM 2800		2800 4000 5000 6000 7000		
			1026°		5.5 NM 4.7 NM 3.8 NM 3.5 NM 3.5 NM		
			275°		GS 3.00° TCH 58		
CATEGORY		A	B	C	D		
S-ILS 27L		RA 214/14 150 DA 1149					



SA CATEGORY I ILS- SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED

HARTSFIELD-JACKSON ATLANTA INTL (ATL)

33°38'N-84°26'W

ILS RWY 27L (SA CAT I)

SE-4, 30 NOV 2023 to 28 DEC 2023