

TACAN RWY 5R

TACAN FFO
Chan 29

APCH CRS
048°

Rwy Ldg
THRE 807
Arpt Elev 823

AL-108 [USAF]

WRIGHT-PATTERSON AFB (KFFO)

* When Rwy 23R VGSi inop, circling to Rwy 23R NA at night.

MISSED APPROACH: Climb to 2000 via FFO R-048 to HOLKU, turn right direct CLACK climbing to 3100 and hold.

ATIS
124.475 269.9

COLUMBUS APP CON
118.85 269.275

PATTERSON TOWER
126.9 281.45

GND CON
121.8 335.8

1250

PATTERSON
Chan 29 FFO

HOLD 6000 3100 FFO 17

100° 265K 280° (IAF) CLACK FFO 12

MSA FFO 2.5 NM 3100

2049 1393 1105 1028 1299 1048 1110 1200 1467 1463 3100 FFO 12 Arc

R-228 048° 048° R-048

BENJJ FFO 12

GRIFF FFO 5

HOLKU FFO 5

CLACK FFO 12

2000 FFO R-048

3100 CLACK FFO 12

6000 3100

GRIFF to RW5R 3.20° TCH 51

4.5 NM 0.6

2600 048°

BENJJ R-228 12 Arc

GRIFF 5

TACAN CUSAD 0.3

GRIFF to RW5R 3.20° TCH 51

12 600 300 7500 x 150

048°

23R 23L 977 980 TWIR

CATEGORY	A	B	C	D	E
S-5R	1500-1	687 (700-1)	1500-2	687 (700-2)	
CIRCLING*	1500-1	677 (700-1)	1560-2 737 (800-2)	1620-2½ 797 (800-2½)	1620-2¾ 797 (800-2¾)

DAYTON, OHIO
Amdt 5 05JAN17

39° 50'N-84° 03'W

WRIGHT-PATTERSON AFB (KFFO)

ELEV 823

THRE 807

HIRL Rwy 5L-23R
MIRL Rwy 5R-23L

TACAN RWY 5R

EC-2, 30 NOV 2023 to 28 DEC 2023

EC-2, 30 NOV 2023 to 28 DEC 2023