




ARRIVAL ROUTE DESCRIPTION

ANAHO TRANSITION (ANAHO.SLMR5)

CARVW TRANSITION (CARVW.SLMR5)

CRAZY TRANSITION (CRAZY.SLMR5)

DONNR TRANSITION (DONNR.SIMMR5)

WFERGO TRANSITION (WFERGO SIMMR.5)

From SLMMR on track 239° to cross POZUR at or above 8000.

LANDING RUNWAYS 17L/R: From POZUR on track 238° to cross TENCO at 4000, then on track 255°. Expect RADAR vectors for assigned instrument approach procedure.

LANDING RUNWAYS 35L/R: From POZUR on track 240° to RICEE, then on track 219° to cross PKAAY at or above 6000 and at 210K, then on track 221° to THANN, then on track 168° to cross BANZA at 4000 and at 210K, then on track 168°

NOTE: Chart not to scale.

SW-2, 30 NOV 2023 to 28 DEC 2023