

---

**ST MARY'S CO RGNL** (See LEONARDTOWN on page 110)

---

**SALISBURY**

WASHINGTON

**BENNETT** (1N5) 4 NW UTC-5(-4DT) N38°24.77' W75°37.02'

46 B NOTAM FILE DCA

**RWY 17-35:** 3171X95 (TURF) LIRL**RWY 17:** APAP(PNIL)—GA 4.0° TCH 23'. Thld dsplcd 240'. Road.**RWY 35:** APAP(PNIL)—GA 5.0°. Thld dsplcd 941'. Road.**RWY 08-26:** 2302X95 (TURF)**RWY 08:** Thld dsplcd 800'. Road.**RWY 26:** Thld dsplcd 300'. Road.**SERVICE:** LGT Dusk-0400Z‡. Actvlt LIRL Rwy 17-35 and bcn—CTAF.**AIRPORT REMARKS:** Attended dawn-dusk. Ultralight act on and invof arpt. Birds and wildlife on and invof arpt. +375 ft lgtd ant 3200 ft L of Rwy 35 thr on L downwind. Rwy 08 and Rwy 26 dthr mkd with 3 orange cones. Rwy 17 and Rwy 35 thr and dthr mkd with lgts and cones. Rwy 17-35 +60 ft trees mid-point both sides of rwy. +70' trees mid-point both sides rwy 17-35.**AIRPORT MANAGER:** (443) 880-7428**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **PATUXENT APP/DEP CON** 127.95 (1200-0400Z‡ Mon-Sun. Other times by NOTAM) other times ctcⓇ **POTOMAC APP/DEP CON** 127.2**CLEARANCE DELIVERY PHONE:** For CD ctc Patuxent Apch at 301-342-3740, when Patuxent Apch is clsd ctc Potomac Apch at 866-640-4124.