

**OGDENSBURG INTL** (OGS)(KOGS) 2 SE UTC-5(-4DT) N44°40.94' W75°27.80'  
 302 B AOE ARFF Index—See Remarks NOTAM FILE OGS  
**RWY 09-27:** H6400X150 (ASPH-GRVD) S-114, D-151, 2D-225

**MONTREAL**  
**H-11C, 12K, L-32G**  
**IAP, AD**

PCR 523 F/D/X/T. HIRL  
**RWY 09:** PAPI(P4L)—GA 3.0° TCH 46'.  
**RWY 27:** MALSf. PAPI(P4L)—GA 3.0° TCH 45'.

**RUNWAY DECLARED DISTANCE INFORMATION**  
**RWY 09:** TORA-6400 TODA-6400 ASDA-6006 LDA-6006  
**RWY 27:** TORA-6400 TODA-6400 ASDA-6035 LDA-6035

**SERVICE:** FUEL 100LL, JET A LGT ACTIVATE MALSf RWy 27; PAPI RWy 09 & 27; HIRL RWy 09-27; Twy lghts—CTAF.

**AIRPORT REMARKS:** Attended Nov 15-Apr 14 1100-0130Z‡, Apr 15-Nov 14 1230-0130Z‡. For attendant aft 0100Z‡ call 315-869-2676. Birds and deer on or invof arpt. Fuel avbl after 2100Z‡ call 315-869-2676. Class I, ARFF Index A. PPR 24 hrs for unsched acro ops with more than 30 pax seats, call amgr. ARFF Index B coverage is avbl upon req. Rwy/twy/apn cond not monitored outside nml attendance hrs. AOE free except Sun after 0500Z‡ and hol. Ldg Fee arpt. Flight Notification Service (ADCUS) avbl.


**AIRPORT MANAGER:** (315) 869-2676  
**WEATHER DATA SOURCES:** AWOS-3 118.525 (315) 393-8982.  
**COMMUNICATIONS:** CTAF/UNICOM 122.8  
 RCO 122.4 (BURLINGTON RADIO)

Ⓡ **BOSTON CENTER APP/DEP CON** 135.25

**CLEARANCE DELIVERY PHONE:** For CD if una to ctc on FSS freq, ctc Boston ARTCC at 603-879-6859.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE MSS.

**MASSENA (H) TACAN** Chan 88 MSS (114.1) N44°54.87' W74°43.36' 260° 34.6 NM to fld. 198/14W.  
**OGIVE NDB (LOMW)** 358 OG N44°42.09' W75°21.18' 269° 4.9 NM to fld. 358/13W. NOTAM FILE OGS.  
**LOC/DME** 110.7 I-OGS Chan 44 RWy 27. LOM OGIVE NDB. Loc/LOM unmonitored.

**COMM/NAV/WEATHER REMARKS:** Acft approaching from the west and landing on Rwy 09 should monitor Brockville Arpt (CNL3) UNICOM on 123.0.



**OGIVE** N44°42.09' W75°21.18' NOTAM FILE OGS.  
**NDB (LOMW)** 358 OG 269° 4.9 NM to Ogdensburg Intl. 358/13W.

**MONTREAL**  
**L-32G**

**OLCOTT-NEWFANE** (D8Ø) 2 SW UTC-5(-4DT) N43°19.25' W78°43.74'  
 315 NOTAM FILE BUF  
**RWY 09-27:** 2500X60 (TURF)

**DETROIT**

**RWY 09:** Trees.  
**RWY 27:** Tree.  
**RWY 06-24:** 2408X30 (TURF)  
**RWY 06:** Trees.  
**RWY 24:** Trees.

**AIRPORT REMARKS:** Attended dalgt hrs. Arpt CLOSED indef. Deer on and invof arpt. 35 ft p-line off Rwy 24 and 27 ends. Rwy 06: 72'-80' trees; across thld and along sides of rwy for 800'. Rwy 09: 31'-100' trees, across thld and along sides of rwy for 600'. Rwy 09-27 ruf and uneven.

**AIRPORT MANAGER:** 716-778-6700  
**COMMUNICATIONS:** CTAF/UNICOM 122.7  
**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland ARTCC at 440-774-0490.