

MAZAMA

LOST RIVER (W12) 5 NW UTC-8(-7DT) N48°38.98' W120°30.12'

SEATTLE

2415 NOTAM FILE SEA

RWY 11-29: 3150X85 (TURF-GRVL)

RWY 11: Road. Rgt tfc.

RWY 29: Road.

AIRPORT REMARKS: Unattended. Arpt CLOSED 1 Nov thru 1 Apr. Watch for vehicles and pedestrians on rwy. Access roads both side of rwy in primary surface, vehicles cross rwy at various locations, primarily at rwy ends.

AIRPORT MANAGER: (206) 321-2447

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

MCCHORD FLD (JOINT BASE LEWIS-MCCHORD) (TCM)(KTCM) AF 3 S UTC-8(-7DT) N47°08.26'

SEATTLE

W122°28.59'

H-1B, L-1D

322 B TPA—See Remarks AOE NOTAM FILE TCM Not insp.

DIAP, AD

RWY 16-34: H10108X150 (ASPH-CONC-GRVD) PCN 60 F/A/W/T HIRL CL

RWY 16: ALSF1. PAPI(P4L)—GA 3.0° TCH 68'. RVR-T 0.4% up.

RWY 34: ALSF2. TDZL. PAPI(P4L)—GA 3.0° TCH 59'. RVR-T Rgt tfc.

RWY 162-342: H3000X60 (ASPH)

ARRESTING GEAR/SYSTEM

RWY 16 HOOK E5 (240' OVRN) HOOK BAK-12B(B) (2450'). HOOK BAK-12B(B) (1668') HOOK E5 (102' OVRN) **RWY 34 SERVICE:** S4 **OX** 1, 2 **LGT** Visual TCH set for hgt Gp 3 acct only. Rwy 16-34 cntr 72' thld lgt removed. AMP-1/AMP-3 overt/covert assault strip lgt inst mid 5000' Rwy 16-34. **MILITARY— JASU** (MD-3M) 1(MD-3) 1(MA-1A) (AM32A-60) 1(MC-11) **FUEL** A++ **FLUID** SP PRESAIR De-ice-Exp 3 hr delay. LHOX LOX **OIL** 0-128-133-148-156 SOAP - Results rqr 24 hr, 1530-0030Z± wkd exc hol, results not avbl OT. Tran acct req SOAP will arr with historical eng SOAP data for trend analysis. **TRAN ALERT** Opr H24. Delays can be exp. Prk ltd. All tran acct rqr tran alert follow me assistance.

MILITARY REMARKS: All twy edge lgt and Rwy 16-34 edge, cntrln, TDZ lgt equipped with nstd LED fixtures may not be compatible with all NVDs or enhanced flight vision systems. **RSTD** All acct inc sked AMC msn rqr PPR 24 hr prior to arr. PPR's effective +/- 1 hr. Tran acct park extremely ltd. Msn planners must ctc AMOPS when using McChord as divert base. AMOPS DSN 382-5611, C253-982-5611. Acft RON more than 3 days and/or rqr other than normal trans svc must ctc 62 AW/XP, 253-982-5890. All inbd acct must ctc Comd Post (Rainier Ops) no later than 30 min prior to ldg. AMC acct opr rstd dur Bird Watch Cond Moderate (tkf and ldg permission only when departing/arr tbe avoid identified bird acct, no lcl IFR/VFR tfc pat acct) and Severe (tkf and ldg prohibited without OG/CC apvl), ctc PTD/ATIS/Command Post for current Bird Watch Cond. Tran aircrews conducting lcl area low-level training msn must receive lcl procedure/rstd briefing from 62 OSS/OSK at DSN 382-3615, C253-982-3615. **CAUTION** When performing pre-tkof end runup, align acct so that debris is not blown toward ADTAC alert hgr or adj acct prk ramp. Dur VFR cond, acct making lo apch, nml tkof, touch and go ldg, or missed apch remain at or blw 1800 ft til dep end of the rwy. Bird haz. South end rwy not visible from official wx station obsn point. When fog/low clouds are present over AER 34, cond report from obsn point may not be representative. **CSTMS/AG/IMG** Unsked acct arr btn 0900-1400Z± may experience delays for CSTMS/AG/IMG inspections. **TFC PAT** Before ldg maintain tfc pat all commensurate with safety as long as practicable. TPA—Rectangular 1800' (1478) overhead 2300' (1978). **MISC** Aircrews notify PTD anytime they plan to delay in lcl IFR pat on separate clnc prior to or departure on filed flt plan. Base OPS DSN 382-5611, C253-982-5611. Rwy 16-34 marked with white non-reflective 90' x 3500' VFR daytime assault ldg zone. South 1000' Rwy 16-34 is conc, rwy is grnd. Rwy cond codes (RWYCC) unavbl.

AIRPORT MANAGER: 253-982-5611

WEATHER DATA SOURCES: ASOS (253) 982-3434

COMMUNICATIONS: D-ATIS 135.825 270.1 PTD 372.2

Ⓡ SEATTLE APP/DEP CON 126.5 377.15

TOWER 124.8 259.3 **GND CON** 118.175 279.65

COMD POST 349.4 134.1

PMSV METRO 342.3 Wx svc avbl 1200-0500Z±; ltd duty fcst 0500-1200Z±. DSN 382-3434/2112, C253-982-3434/2112. All obs provided by AN/FMQ-19 automated observing sys; augmented by human obsn when nec. Full svc PMSV avbl via phone patch with comd post. Tran aircrew ctc 25 OWS dur lcl closure to request wx briefing DSN 228-6598, or C520-228-6598. when possible provide 3 hr pn for all rqr briefings.

AIRSPACE: CLASS D.

RADIO AIDS TO NAVIGATION: NOTAM FILE TCM.

(T) **TACAN** Chan 33 TCM (109.6) N47°08.86' W122°28.50' at fld. 283/15E.

No NOTAM MP 0800-2300Z± Wed

ILS 109.9 I-MAR Rwy 16. Class 1A. Rwy 16-34 backcourse unusable. Rwy 16-34 No NOTAM MP

0800-2300Z± Tue and Thu.

ILS 108.5 I-TCM Rwy 34. Class IIE. Rwy 16-34 backcourse unusable. Rwy 16-34 No NOTAM MP 0800-2300Z±

Tue and Thu.