

AZTEC MUNI (N19) 2 NW UTC-7(-6DT) N36°50.22' W108°01.72'

5882 B NOTAM FILE ABQ

DENVER

L-8I

RWY 08-26: H4314X60 (ASPH) S-10 PCN 4 F/C/Y/T MIRL 0.4% up E

RWY 08: ODALS (NSTD) APAP(PNIL)—GA 3.5° TCH 30'. Thld dsplcd 226'.

RWY 26: ODALS (NSTD) PVASI(PSIL)—GA 3.0° TCH 20'. Thld dsplcd 277'.

SERVICE: FUEL 100LL LGT Rwy 08-26 MIRL on dusk-0530Z‡ and 1100Z‡-Dawn. ACTVT Rwy 08 and Rwy 26 ODALS; Rwy 26 PLASI; Rwy 08-26 MIRL—CTAF. Rwy 08 NSTD ODALS; one each side. Rwy 26 NSTD ODALS; 2 omni strobes each side and 1 omni strobe on cntrln 15 ft fm EOR.

AIRPORT REMARKS: Unattended. Emerg—505-334-6622 police. Gate aces 1987#. 100LL fuel automated. Rwy 26 preferred ngt ops. Lctd atop mesa. 4 ft fence 105 ft fm cntrln intmt alg rwy both sides. 60-180 ft trrn drop off byd rwy ends. Runups on turn arounds NA.

AIRPORT MANAGER: (505) 334-7688

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE FMN.

RATTLESNAKE (VH) (H) VORTAC 115.3 RSK Chan 100 N36°44.90' W108°05.93' 019° 6.3 NM to fld.
5821/14E.

VOR unusable:

007°-017° byd 40 NM blo 18,000'

018°-041° byd 40 NM

042°-062° byd 40 NM blo 15,000'

042°-062° byd 63 NM blo 20,000'

063°-066° byd 40 NM

067°-077° byd 40 NM blo 14,000'

067°-077° byd 75 NM

078°-094° byd 40 NM

095°-105° byd 40 NM blo 18,000'

106°-119° byd 40 NM blo 11,500'

106°-119° byd 62 NM blo 12,500'

106°-119° byd 76 NM

120°-125° byd 40 NM

235°-255° byd 40 NM blo 12,000'

235°-255° byd 84 NM blo 28,000'

256°-274° byd 40 NM

275°-285° byd 40 NM blo 30,000'

286°-327° byd 40 NM

328°-338° byd 40 NM blo 15,000'

344°-356° byd 40 NM blo 16,300'

344°-356° byd 66 NM

357°-006° byd 40 NM