

WAAS CH 53512 W10A	APP CRS 104°	Rwy Idg TDZE Apt Elev 4001 1057 1074	RNAV (GPS) Z RWY 10 MOUNT WASHINGTON RGNL (HIE)
--	------------------------	--	---

▼


▲

❄

DME/DME RNP-0.3 NA. Visibility reduction by helicopters NA.
When local altimeter setting not received, use Lyndonville altimeter
setting and increase DA 71 feet and LPV all Cats visibility ½ mile.

MISSED APPROACH: Climb to 7100 direct
CRESY and via track 099° to JOBBY and
hold, continue climb-in-hold to 7100.

ASOS 118.525	BOSTON CENTER 135.7 282.2	UNICOM 122.8 (CTAF) 1
------------------------	-------------------------------------	---------------------------------



ELEV 1074

TDZE 1057

104°

0.6% UP

4001 X 75

28

5 NM

Holding Pattern

VGSI and RNAV glidepath not coincident (VGSI Angle 3.50/TCH 45).

5 NM

LIDOW

4800

284°

104°

104°

3400

ELJUM

3400

RW10

6.1 NM

7.1 NM

GP 3.00°

TCH 45

7100

CRESY

tr 099°

JOBBY

CATEGORY	A	B	C	D
*LPV DA	1507-1½ 450 (500-1½)			
	NA			

REIL Rwy 10 and 28 1

MIRL Rwy 10-28 1