AI ASKA 93

171° 49.5 NM

DEERING (DEE)(PADE) 2 SW UTC-9(-8DT) N66°04.15′ W162°46.02′

30 B NOTAM FILE DEE

RWY 03-21: 3320X75 (GRVL) MIRI

RWY 03: REIL. PAPI(P4R)-GA 3.0° TCH 25'.

RWY 12-30: 2660X75 (GRVL) MIRL 0.4% up NW

SERVICE: LGT ACTIVATE MIRL Rwy 03-21 and Rwy 12-30; REIL Rwy 03 and PAPI Rwy 03 -CTAF. ACTIVATE rotating bcn -CTAF.

AIRPORT REMARKS: Unattended, Migratory birds as well as musk oxen and other large animals on and invof of rwys. Rwy cond not monitored. recommend visual inspection prior to ldg. Cold temperature airport. Altitude correction required at or below -40C. Rwy 03-21 plowed in winter. Windsock missing at Rwy 12. Rwy 03-21 NSTD markings, marked with lgts and plastic markers. Rwy 12-30 NSTD markings, marked with lgts and plastic markers.

AIRPORT MANAGER: 907-442-3147

WEATHER DATA SOURCES: ASOS 135.5 (907) 363-2102. (WX CAM)

COMMUNICATIONS: CTAF 122 9

DEERING RCO 122.25 (KOTZEBUE RADIO) ANCHORAGE CENTER APP/DEP CON 119.2 263.0 RADIO AIDS TO NAVIGATION: NOTAM FILE OTZ.

KOTZEBUE (H) (H) VORW/DME 115.7 OTZ Chan 104 N66°53.14′ W162°32.40′ 171° 49.5 NM to fld. 121/15E.

COMM/NAV/WEATHER REMARKS: For a LC to Kotzebue FSS dial 907-442-3310. For a toll free call to Kotzebue FSS dial 1-800-478-7460. For a toll free call to Fairbanks FSS dial 1-866-248-6516.

From Kotzebue "OTZ" VOR/DME · Tundra

DELTA DAVES (See DELTA JUNCTION on page 93)

## **DELTA JUNCTION**

ALL WEST (AK77) PVT 11 E UTC-9(-8DT) N63°56.49′ W145°25.33′ 1275 NOTAM FILE Not insp.

ANCHORAGE H-1B. L-1A. 3B. 3E

NOME

I \_4H

IAP

RWY 09-27: 5500X75 (TURF-GRVL) AIRPORT REMARKS: Unattended AIRPORT MANAGER: 907-895-9800

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.

**DELTA DAVES** (AA22) PVT 7 NW UTC-9(-8DT) N64°07.97′ W145°48.27′

FAIRBANKS

1050 NOTAM FILE Not insp.

RWY 15-33: 2350X60 (TURF)

RWY 15: Trees.

RWY 33: Rgt tfc.

AIRPORT REMARKS: Unattended. AIRPORT MANAGER: 907-895-4887

 ${\tt COMM/NAV/WEATHER\ REMARKS:}$  For a toll free call to Fairbanks FSS dial 1-866-248-6516.

FAIRBANKS

**DELTA JUNCTION** (D66) 1 N UTC-9(-8DT) N64°03.01′ W145°43.35′

1150 NOTAM FILE FAI RWY 07-25: 2500X60 (GRVI)

RWY 07: Trees.

RWY 25: Trees. Rgt tfc.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to use. Rwy within 5 miles of Allen Army arfld. Rwy 07 p-line W of rwy marked with orange balls. Clnc slope to p-line 33:1. 335' Igtd twr 1 mi S of arpt. Arpt and electricity usage fees apply. Ctc arpt mgmt. Rwy 07-25 edges marked with reflective cones. Transient parking on East end, South side of Rwy 07. Personnel and eqpt may be working on the rwy at any time.

AIRPORT MANAGER: 907-460-6688

**COMMUNICATIONS: CTAF** 122.9

SUAIS 125.3 126.3 (1-800-758-8723).

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.