

LIVINGSTON CO SPENCER J HARDY (OZW)(KOZW) 3 NW UTC-5(-4DT) N42°37.77' W83°58.93' **DETROIT COPTER**
 962 B TPA—2001(1039) NOTAM FILE OZW MON Airport
RWY 13-31: H5002X100 (CONC-GRVD) S-100 HIRL 0.4% up NW **H-10G, L-28J IAP**
RWY 13: MALSR. PAPI(P4L)—GA 3.0° TCH 47'. Trees.
RWY 31: REIL. PAPI(P4L)—GA 3.0° TCH 30'. Tree.

SERVICE: S4 **FUEL** 100LL, JET A, A+ **LGT** HIRL Rwy 13-31 ops low ints dusk-0300Z; to increase ints and **ACTIVATE** after 0300Z—CTAF. **ACTIVATE** REIL Rwy 31 and MALSR Rwy 13—CTAF. PAPI Rwy 13 and Rwy 31 ops dawn-dusk, thereafter—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1200-2200Z, Sat-Sun 1300-1700Z. Deer and large birds on and invof arpt.

AIRPORT MANAGER: 517-546-6675

WEATHER DATA SOURCES: AWOS-3 118.875 (517) 546-4450.

COMMUNICATIONS: CTAF/UNICOM 123.0

Ⓡ **DETROIT APP/DEP CON** 132.35

CLNC DEL 121.725

GCO 121.725 (DETROIT METRO CLNC and FLIGHT SERVICES)

CLEARANCE DELIVERY PHONE: For CD ctc Detroit Apch at 734-955-1404.

RADIO AIDS TO NAVIGATION: NOTAM FILE LAN.

SALEM (L) (L) VORTACW 114.3 SVM Chan 90 N42°24.52' W83°35.63' 311° 21.7 NM to fld. 956/3W.

TACAN AZIMUTH unusable:

215°-255° byd 10 NM

VOR unusable:

094°-121° byd 10 NM blo 5,000'

094°-121° byd 20 NM blo 8,000'


DME unusable:

099°-115° byd 15 NM blo 5,000'

099°-115° byd 20 NM blo 8,000'

ILS/DME 108.55 I-OGO Chan 22(Y) Rwy 13. ILS/DME unmonitored. DME unusable byd 25° right of course.

COMM/NAV/WEATHER REMARKS: For Clnc Del key frequency 121.725 4 times. To contact FSS key frequency 121.725 6 times; one second on/one second off; monitor 121.725 while electronic equipment dials DET Clnc Del/Lansing FSS.



RAETHER (4Y1) 6 SE UTC-5(-4DT) N42°33.92' W83°51.38' **DETROIT COPTER**
 984 NOTAM FILE LAN
RWY 17-35: 2206X70 (TURF)

RWY 17: Thld dspclcd 757'. Trees.

RWY 35: Thld dspclcd 740'. Road.

AIRPORT REMARKS: Unattended. Lrg birds and deer on and invof arpt. Ultralight act on and invof arpt. Hvy eqpt adj to west side of Rwy 35. Rwy 17-35 thld and dthr mkd with 3' cones.

AIRPORT MANAGER: 517-546-4498

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Detroit Apch at 734-955-1404.

HURON CO MEML (See BAD AXE on page 156)

INDIAN RIVER

CAMPBELL-PRATT (Y65) 1 E UTC-5(-4DT) N45°24.37' W84°35.90' **LAKE HURON L-3IC**
 614 NOTAM FILE LAN

RWY 10-28: H3005X50 (ASPH) LIRL

RWY 10: Trees.

RWY 28: Thld dspclcd 600'. Trees.

SERVICE: **LGT** **ACTIVATE** LIRL Rwy 10-28—CTAF.

AIRPORT REMARKS: Attended irregularly. Deer and lrg birds on and invof arpt. For svc ctc amgr. Snow removal intmt call amgr to vfy conds.

AIRPORT MANAGER: 586-899-8115

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE PLN.

PELLSTON (L) (L) VORTACW 111.8 PLN Chan 55 N45°37.84' W84°39.85' 174° 13.8 NM to fld. 836/6W.

VOR unusable:

301°-339°

GCP has azm only, no DME at GCP