

**MARION MUNI** (MNN)(KMNN) 3 NE UTC-5(-4DT) N40°36.98' W83°03.81'

993 B TPA—1793(800) NOTAM FILE MNN

**RWY 07-25:** H5000X100 (ASPH-GRVD) S-70, D-95, 2S-121, 2D-150 MIRL

**RWY 07:** REIL. PAPI(P4L)—GA 3.0° TCH 24'. Road.

**RWY 25:** REIL. PAPI(P4L)—GA 3.0° TCH 31'. Trees.

**RWY 13-31:** H3498X100 (ASPH-GRVD) S-56, D-68, 2S-86, 2D-105 MIRL

**RWY 13:** REIL. PAPI(P2R)—GA 3.0° TCH 21'. Trees.

**RWY 31:** REIL. PAPI(P2L)—GA 3.0° TCH 21'. P-line.

**SERVICE:** S4 FUEL 100LL, JET A1, A1+ LGT After 0500Z† ACTIVATE REIL Rwy 07, 25, 13 and Rwy 31; MIRL Rwy 07-25 and Rwy 13-31—CTAF. PAPI Rwy 07, 25, 13 and Rwy 31 opr consly.

**AIRPORT REMARKS:** Attended 1300-2200Z†. Ocnl deer, birds and other wildlife on and invof arpt. Glider act on and invof arpt, annc intns—CTAF. Rwy 07 and Rwy 31 gliders and towplanes use rgt tfc. 100 LL avbl H 24 self serv via credit card. Jet A avbl aft hrs by prior cdn. Tsnt acct follow ramp signs to main ramp. Twy D btn rwy and ramp area rstrd to acct with wingspan 35' or less.

**AIRPORT MANAGER:** 740-382-1634

**WEATHER DATA SOURCES:** ASOS 119.975 (740) 223-7502. SAWRS.

**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓡ CLEVELAND APP/DEP CON 124.2 (1100-0600Z‡)

Ⓡ CLEVELAND CENTER APP/DEP CON 135.1 (0600-1100Z‡) ctc Cleveland ARTCC at 440-774-0223.

CLNC DEL 126.8

**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at 440-774-0222.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE MFD.

**MANSFIELD (L) (L) VORTACW** 108.8 MFD Chan 25 N40°52.12' W82°35.46' 238° 26.3 NM to fld. 1222/3W.

TACAN AZIMUTH unusable:

075°-095°

151°-214° byd 30 NM

VOR unusable:

151°-214° byd 15 NM

DME unusable:

151°-214° byd 30 NM

**BUCKEYE (T) VORW** 109.8 BUD N40°37.00' W83°03.83' at fld. 989/5W. NOTAM FILE MNN.

**DETROIT**

H-106, L-29A

IAP

## MARYSVILLE

**UNION CO** (MRT)(KMRT) 1 SE UTC-5(-4DT) N40°13.47' W83°21.10'

1021 B NOTAM FILE DAY

**RWY 09-27:** H4218X75 (ASPH) S-17 MIRL 0.6% up W

**RWY 09:** REIL. PAPI(P4L)—GA 3.0° TCH 25'.

**RWY 27:** REIL. PAPI(P4L)—GA 3.0° TCH 33'. Thld dsplcd 123'. Railroad.

**RWY 08-26:** 2702X81 (TURF) 0.8% up W

**SERVICE:** S4 FUEL 100LL, JET A1, A1+ LGT Actvt REIL Rwy 09 & 27; PAPI Rwy 09 & 27; MIRL Rwy 09-27—CTAF.

**AIRPORT REMARKS:** Attended 1300-2200Z†. Rgt tfc: ck NOTAMS for sts of aerobatic box South of Rwy 09-27 & Rwy 08-26 — RP Rwy 27 & 26 when actv. Deer, birds, and otr wildlife on & invof arpt. Fuel avbl 24 hrs self ser via credit card. Rwy 08 thr & edges mkd with cones. Rwy 26 thr & edges mkd with cones. Rwy 09 calm wind rwy. Ramp fee for coml acct.

**AIRPORT MANAGER:** 937-644-2055

**WEATHER DATA SOURCES:** AWOS-3 119.275 (937) 644-2967.

**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓡ COLUMBUS APP/DEP CON 125.95

**CLEARANCE DELIVERY PHONE:** For CD ctc Columbus Apch at 614-338-8537.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE DAY.

**ROSEWOOD (H) (H) VORTACW** 117.5 ROD Chan 122 N40°17.27' W84°02.59' 102° 32.0 NM to fld. 1080/5W.

TACAN AZIMUTH unusable:

000°-120°

125°-135°

VOR unusable:

125°-135°

**DETROIT**

L-29A

IAP

**MAYFIELD** (See AKRON on page 258)