

MIDDLE BASS—EAST POINT (3W9) 1 NE UTC-5(-4DT) N41°41.67' W82°47.79' **DETROIT**
 582 NOTAM FILE CLE
RWY 09-27: 2085X67 (TURF)
RWY 09: Berm.
RWY 27: Road. Rgt tfc.
AIRPORT REMARKS: Attended May-Oct ired, unatndd Nov-Apr. Ocnl deer, birds and otr wildlife on and invof arpt. Rwy 09-27 soft and wet in spring. Nmrs trees and bldgs in close proximity to rwy. Exp sgfnt ws and turb on apch and dep when wind exceeds 10 Kt. For wind indir use segmented crc at 3T7 arpt.
AIRPORT MANAGER: 216-870-6513
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323.

MIDDLE BASS—EAST POINT (See MIDDLE BASS ISLAND on page 302)

MIDDLEFIELD

GEAUGA CO (7G8) 1 SE UTC-5(-4DT) N41°26.98' W81°03.78' **DETROIT**
 1174 B TPA-2199(1025) NOTAM FILE CLE **L-30G**
RWY 11-29: H3500X65 (ASPH) S-18.5 MIRL 0.5% up W **IAP**
RWY 11: REIL. Thld dsplcd 179'. Antenna.
RWY 29: REIL. PAPI(P2L)—GA 3.0° TCH 23'.
SERVICE: FUEL 100LL, MOGAS LGT ACTIVATE REIL Rwy 11 & Rwy 29; PAPI Rwy 29; MIRL Rwy 11-29—CTAF.
AIRPORT REMARKS: Attended Mon-Fri 1400-2200Z† ired. Deer, birds & otr wildlife on and invof arpt. Extsv glider act on and invof arpt. Parl twy east of tee hngrs clsd prmly. Fuel: 100LL avbl H24 via credit card.
AIRPORT MANAGER: 440-632-1884
COMMUNICATIONS: CTAF/UNICOM 123.0
 Ⓡ **CLEVELAND APP/DEP CON** 125.35
CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323.
RADIO AIDS TO NAVIGATION: NOTAM FILE CLE.
CHARDON (H) (DH) VOR/DME 112.7 CXR Chan 74 N41°31.02' W81°09.79' 137° 6.1 NM to fld. 1317/5W.
 VOR unusable:
 074°-084° byd 10 NM blo 3,300'
 085°-099° byd 10 NM blo 11,000'
 104°-180° byd 10 NM blo 6,000'
 357°-073° byd 10 NM blo 11,000'
 DME unusable:
 019°-029° byd 34 NM blo 3,700'
 158°-174° blo 5,500'
 253°-274° blo 4,100'
COMM/NAV/WEATHER REMARKS: Adzy only wx avbl - 4 clicks CTAF.

MIDDLETOWN RGNL/HOOK FLD (MWO)(KMW0) 2 N UTC-5(-4DT) N39°31.91' W84°23.79' **CINCINNATI**
 651 B TPA—See Remarks NOTAM FILE DAY **H-10G, L-27E**
RWY 05-23: H6100X100 (ASPH) S-66, D-78, 2S-99, 2D-140 MIRL **IAP**
RWY 05: REIL. PAPI(P4R)—GA 3.0° TCH 22'. Trees.
RWY 23: REIL. PAPI(P4R)—GA 3.0° TCH 26'. Thld dsplcd 299'. Tree. Rgt tfc.
RWY 08-26: 3026X160 (TURF)
RWY 08: Thld dsplcd 951'. Trees.
RWY 26: Rgt tfc.
SERVICE: S4 FUEL 100LL, JET A+ **OX 4** LGT ACTIVATE REIL Rwy 05 and Rwy 23; MIRL Rwy 05-23—CTAF. PAPI Rwy 05 and Rwy 23 opr consly.
AIRPORT REMARKS: Attended 1200-2400Z†. Deer, birds, & otr wildlife on & invof arpt. Extensive Parachute Jumping. Ultralights enter/exit Rwy 08 tfc pat fm/to the North at lwr than rglr TPA. Ultralights do not fly south of Rwy 26. Rwy 08-26 end mkg white cones.
AIRPORT MANAGER: 513-422-9750
WEATHER DATA SOURCES: AWOS-3PT 120.025 (513) 422-3505.
COMMUNICATIONS: CTAF/UNICOM 123.0
 Ⓡ **COLUMBUS APP/DEP CON** 118.85
CLEARANCE DELIVERY PHONE: For CD ctc Columbus Apch at 614-338-8537.
RADIO AIDS TO NAVIGATION: NOTAM FILE HUF.
RICHMOND (L) DME 110.6 RID Chan 43 N39°45.30' W84°50.33' 123° 24.5 NM to fld. 1135.
ONIDA NDB (LOMW) 223 MW N39°34.69' W84°19.41' 235° 4.4 NM to fld. 684/4W. NOTAM FILE DAY. NDB unmonitored.
 NDB unusable:
 060°-090° byd 10 NM
LOC 111.1 I-MWO Rwy 23. LOM ONIDA NDB. LOM unmonitored.