

**ALTOONA/BLAIR CO** (AOO)(KAOO) 12 S UTC-5(-4DT) N40°17.78' W78°19.20'

DETROIT

1503 B Class II, ARFF Index A NOTAM FILE AOO

H-10H, 12I, L-29D, A

**RWY 03-21:** H5465X100 (ASPH-GRVD) S-16, D-44 PCN 13 F/B/X/T

IAP

HIRL 0.6% up S

**RWY 03:** REIL. PAPI(P4L)—GA 3.0° TCH 43'. Trees.**RWY 21:** MALSR. PAPI(P4L)—GA 3.0° TCH 52'. Trees.**RWY 12-30:** H3668X75 (ASPH) S-11.5, D-33 PCN 11 F/B/X/T MIRL**RWY 12:** REIL. PAPI(P4L)—GA 3.0° TCH 54'. Trees.**RWY 30:** REIL. PAPI(P4R)—GA 4.0° TCH 54'. Tree.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 03:** TORA-5465 TODA-5465 ASDA-5465 LDA-5465**RWY 12:** TORA-3668 TODA-3668 ASDA-3668 LDA-3668**RWY 21:** TORA-5465 TODA-5465 ASDA-5465 LDA-5465**RWY 30:** TORA-3668 TODA-3668 ASDA-3668 LDA-3668

**SERVICE:** S4 FUEL 100LL, JET A OX 1, 3 LGT Rwy 03-21, thld lgts and edge lgts OTS exc with PCL, avbl fm 0100-1300Z† daily. Rwy 12-30, thld lgts and edge lgts OTS exc with PCL avbl fm 0100-1300Z† daily. HIRL Rwy 03-21 and MIRL Rwy 12-30 preset low instst, incr instst and ACTVT PAPI Rwy 12, 30, 03 and 21, MALSR Rwy 21 and REIL Rwy 03, 12 and 30—CTAF.

**NOISE:** Preferred rwy is Rwy 21; for noise abatement when departing Rwy 03, maintain rwy heading until 2 NM north of arpt.

**AIRPORT REMARKS:** Attended Mon-Fri 0930-0330Z†, Sat 1230-0030Z†, Sun 1330-0130Z†. Rwy/twy conds unmonitored outside of normal attendance hrs. Specialized acft (ultralgt, homebuilt, etc) ctc amgr 814-793-2027 or UNICOM prior to Idg. PPR 24 hrs for unscheduled air carrier and non-air carrier ops with more than 30 passenger seats call arpt manager 814-793-2027. Excp for taxi, Rwy 12-30 not avbl for sked acr ops with more than 9 pax and unsked for acr ops with more than 30 pax.

**AIRPORT MANAGER:** 814-793-2027**WEATHER DATA SOURCES:** ASOS 127.125 (814) 793-9655.**COMMUNICATIONS:** CTAF 123.6

RCO 122.2 (ALTOONA RADIO)

Ⓡ JOHNSTOWN APP/DEP CON 121.2 (1200-0400Z†)

Ⓡ CLEVELAND CENTER APP/DEP CON 124.4 (0400-1200Z†)

**CLEARANCE DELIVERY PHONE:** For CD ctc Johnstown Apch at 814-532-5960, when Apch clsd ctc Cleveland ARTCC at 440-774-0213.

**AIRSPACE:** CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE AOO.

ST THOMAS (L) TACAN Chan 97 THS (115.0) N39°55.99' W77°57.06' 329° 27.6 NM to fld. 2338/7W.

ILS 111.1 I-AOO Rwy 21. Class IA. LOC unusable byd 25° right of course.

**ARNOLD PALMER RGNL** (See LATROBE on page 294)**BALLY****BUTTER VALLEY GOLF PORT** (7N8) 1 E UTC-5(-4DT) N40°23.85' W75°33.79'

NEW YORK

500 NOTAM FILE IPT

**RWY 16-34:** H2420X85 (ASPH-TURF)**RWY 16:** Thld dsplcd 205'. Road.**RWY 34:** Thld dsplcd 250'. Road.

**AIRPORT REMARKS:** Attended daylight hours. Rwy 16-34 located in middle of golf course. Trees and substantial terrain elevation changes within 125' of each rwy edge. Rwy 16-34 1535 ft X 24 ft asph insert at S end; remainder turf. Rwy 16 marked with yellow wood panels; turf rwy edges marked with tires painted yellow. Rwy 34 dsplcd thld marked with 3 white lines.

Rwy 16 dsplcd thld marked by 3 yellow tires. Rwy 34: 119 ft tree line 1472 ft fm rwy end; 233 ft right. 12:1 slope to dthr.

**AIRPORT MANAGER:** 610-845-2491**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Allentown Apch at 800-728-6322.**BANDEL** (See EIGHTY FOUR on page 279)**BAUBLITZ COMMERCIAL** (See BROGUE on page 271)**BEAVER CO** (See BEAVER FALLS on page 267)