

DANBURY MUNI (DXR)(KDXR) 3 SW UTC-5(-4DT) N41°22.29' W73°28.93'

457 B TPA—See Remarks NOTAM FILE DXR

NEW YORK

L-33B, 341

IAP, AD

RWY 08-26: H4421X150 (ASPH-GRVD) S-38, D-70, 2S-90 MIRL

RWY 08: REIL. Thld dsplcd 367'. Trees.

RWY 26: REIL. Thld dsplcd 734'. Trees.

RWY 17-35: H3135X100 (ASPH) S-50, D-65, 2S-82

RWY 17: Thld dsplcd 223'. Pole.

RWY 35: Thld dsplcd 231'. Trees.

SERVICE: S4 **FUEL** 100LL, JET A **OX 4** **LGT** When twr clsd, ACTIVATE

REIL Rwy 08 and Rwy 26 and MIRL Rwy 08-26—CTAF.

NOISE: Noise abatement procedures in effect ctc arpt manager
203-797-4624.

AIRPORT REMARKS: Attended 1200Z†-dusk. Deer and birds on and in/ovf arpt. Rwy 17-35 CLOSED nghts. Cond unmnt 2130-1230Z† Mon-Fri and wkends. Prohibited to ultralight and unregistered acft. Intersection tkfs, stop and go tkfs not authorized. Acft using Rwy 35 not visible from twr descending below 1300' on base leg until approaching 1/2 mile final due to natural terrain. TPA—2200 (1743) Turboprop/Jet. PPR for formation tkf/lfd, ctc arpt manager. Rotating bcn located one mile south of arpt on top of a hill.

AIRPORT MANAGER: 203-797-4624

WEATHER DATA SOURCES: ASOS 127.75 (203) 791-8227. LAWRS.

COMMUNICATIONS: CTAF 119.4 ATIS 127.75 UNICOM 122.95

® **NEW YORK APP/DEP CON** 126.4

TOWER 119.4 (1200-0300Z†) **GND CON** 121.6 **CLNC DEL** 128.6 (When DXR twr clsd)

AIRSPACE: CLASS D svc 1200-0300Z†; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE ISP.

CARMEL (L) (L) VOR/DME 116.6 CMK Chan 113 N41°16.81' W73°34.88' 051° 7.1 NM to fld. 693/12W.

VOR unusable:

001°-155°

195°-225°

245°-270°

325°-355°

DME unusable:

000°-015° byd 20 NM

034°-054° byd 20 NM

055°-135° byd 20 NM blo 5,000'

180°-200°

340°-359° byd 20 NM blo 6,000'

LOC/DME 111.55 I-DXR Chan 52(Y) Rwy 08. LOC unmonitored when ATCT clsd. Localizer offset angle 3.00 deg.

LOC unusable byd 20° right side of course. DME unusable byd 10 NM; and 10° right of course and byd 20° left of course.

