

FRONT ROYAL—WARREN CO (FRR)(KFRR) 3 W UTC-5(-4DT) N38°55.05' W78°15.20'

WASHINGTON

704 B NOTAM FILE DCA

L-29D, A

Rwy 10-28: H3008X75 (ASPH) S-12.5 MIRL 0.4% up E

Rwy 10: APAP(PNIR)—GA 3.0° TCH 16'. Road.

Rwy 28: APAP(PNIL)—GA 3.0° TCH 16'. Pole.

SERVICE: S2 **FUEL** 100LL **LGT** Actvt MIRL Rwy 10-28—CTAF.

NOISE: Noise abatement procedures in effect, ctc arpt mgr for details at 540-635-3570.

AIRPORT REMARKS: Attended 1400-2200Z±. Deer and geese on and in vof arpt. Glider ops on and in vof arpt. Rwy 10 and Rwy 28 rgt tfc for gyrocopters, ultralights and gliders.

AIRPORT MANAGER: 540-635-3570

WEATHER DATA SOURCES: AWOS-3 121.85 (540) 635-5377.

COMMUNICATIONS: CTAF/UNICOM 123.0

Ⓡ **POTOMAC APP/DEP CON** 120.45

CLEARANCE DELIVERY PHONE: For CD ctc Potomac Apch at 866-709-4993.

RADIO AIDS TO NAVIGATION: NOTAM FILE DCA.

LINDEN (L) (L) VORTACW 114.3 LDN Chan 90 N38°51.26'

W78°12.33' 335° 4.4 NM to fld. 2435/6W.

DME portion unusable:

115°-150° byd 20 NM blo 3,500'

150°-155° byd 20 NM blo 4,000'

155°-175° byd 20 NM blo 4,500'

175°-200° byd 20 NM blo 5,000'

200°-225° byd 20 NM blo 5,500'

TACAN AZIMUTH unusable:

115°-225° byd 20 NM

