

PALAU

ANGAUR ISLAND

ANGAUR AIRSTRIP (ANG) 30 SW UTC+9 N06°54.00' E134°09.00'

20 NOTAM FILE HNL

RWY 05-23: 7000X150 (GRVL)

RWY 05: Trees.

RWY 23: Trees.

AIRPORT REMARKS: Unattended.

COMMUNICATIONS: CTAF 122.9

BABELTHUAP ISLAND

PALAU INTL (ROR)(PTRO) 4 NE UTC+9 N07°22.04' E134°32.66'

177 B NOTAM FILE HNL

RWY 09-27: H7200X150 (ASPH-CONC-PFC) S-75, D-190, 2S-175, 2D-300 MIRL

RWY 09: REIL. PAPI(P4L)—GA 3.0° TCH 52'.

RWY 27: REIL. PAPI(P4L)—GA 3.0° TCH 52'. Trees.

SERVICE: FUEL JET A1 **LGT** For MIRL Rwy 09-27 and rotating beacon contact KOROR RADIO—123.6.

AIRPORT REMARKS: Attended continuously. Be alert to large number of birds on rwy at night. ARFF avbl 24/7. All unscheduled flts must file a flt plan at least 7 days prior to arr and all flts must ctc Koror Communications on 123.6 at least 20 min prior to arr. Entry permit rqr call 011 (680) 488-2498, fax 011 (680) 488-4385; landing permit rqr must give 7 days notice. All acft exceeding 100,000 lbs GWT taxi to thld turn around before taxing to apron. Acft under 100,000 lbs GWT may make a turn around where feasible.

AIRPORT MANAGER: (680) 488-2111

COMMUNICATIONS: CTAF 123.6

KOROR RADIO 123.6 AAS avbl 2 hr prior arr, clsd 1 hr after dep. 2182 5205X.

RADIO AIDS TO NAVIGATION:

KOROR NDB/DME (HW/DME) 371 ROR Chan 104 N07°22.13' E134°33.02' at fld. 183/1E. DME channel 104 paired with VHF freq 115.7

DME unusable:

006°-030° byd 25 NM blo 4,500'

031°-050° byd 25 NM blo 3,500'

051°-220° byd 25 NM blo 2,200'

221°-240° byd 25 NM

241°-290° byd 25 NM blo 3,500'

291°-335° byd 25 NM

336°-005°

COMM/NAV/WEATHER REMARKS: LAA available 2hrs prior to scheduled acft arrival and until 1hr after departure.

KOROR N07°22.13' E134°33.02' NOTAM FILE HNL

NDB/DME (HW/DME) 371 ROR Chan 104 At Palau Intl Airport. 183/1E. DME channel 104 paired with VHF freq 115.7

DME unusable:

006°-030° byd 25 NM blo 4,500'

031°-050° byd 25 NM blo 3,500'

051°-220° byd 25 NM blo 2,200'

221°-240° byd 25 NM

241°-290° byd 25 NM blo 3,500'

291°-335° byd 25 NM

336°-005°

PELELIU (C23) 20 SW UTC+9 N07°00.00' E134°14.00'

9 NOTAM FILE HNL

RWY 04-22: 6000X40 (GRVL)

RWY 04: Trees.

RWY 22: Trees.

AIRPORT REMARKS: Unattended. Rwy 04-22 first 1000' Rwy 04 unusable.

COMMUNICATIONS: CTAF 122.9