


LOC/DME I-CBP 109.1 Chan 28	APP CRS 101°	Rwy Idg 8000 TDZE 815 Apt Elev 815
--	------------------------	---

ILS or LOC RWY 10L


JOHN GLENN COLUMBUS INTL (CMH)

DME or RADAR required.		MALSR	MISSED APPROACH: Climb to 1400 then climbing left turn to 3000 direct APE VORTAC and hold.		
<p>Simultaneous approach authorized.</p> <p>For inop ALS, increase S-LOC 10L Cat C/D visibility to 1 1/2 SM.</p> <p>* RVR 1800 authorized with the use of FD or AP or HUD to DA.</p>					
D-ATIS 124.6	COLUMBUS APP CON 125.95 371.975	COLUMBUS TOWER 132.7 257.8	GND CON 121.9 348.6	CLNC DEL 126.3	CPDLC



EC-2, 13 JUN 2024 to 11 JUL 2024

EC-2, 13 JUN 2024 to 11 JUL 2024



ELEV 815	TDZE 815
TDZ/CL Rwy 10R-28L HRL Rwys 10R-28L and 10L-28R FAF to MAP 4.5 NM	
Knots	60 90 120 150 180
Min:Sec	4:30 3:00 2:15 1:48 1:30