


WAAS CH 40299 W10B	APP CRS 101°	Rwy Idg TDZE Apt Elev	8000 815 815
--	------------------------	-----------------------------	---

RNAV (GPS) Y RWY 10L
JOHN GLENN COLUMBUS INTL (CMH)

RNP APCH	For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -19°C or above 54°C. LNAV procedure NA during simultaneous operations. Use of FD or AP providing RNAV track guidance required during simultaneous operations. Simultaneous approach authorized. For inop ALS, increase LNAV Cat C/D visibility to 1½ SM. # RVR 1800 authorized with use of FD or AP or HUD to DA.	MALSR 	MISSED APPROACH: Climb to 1400 then climbing left turn to 3000 direct APE VORTAC and hold.
----------	---	-----------	--

D-ATIS 124.6	COLUMBUS APP CON 125.95 371.975	COLUMBUS TOWER 132.7 257.8	GND CON 121.9 348.6	CLNC DEL 126.3	CPDLC
------------------------	---	--------------------------------------	-------------------------------	--------------------------	-------



4 NM Holding Pattern	FLANK	CCREW	SILKN	2.5 NM to RW10L	1400	3000	APE
6000 3300	281°	2300	2300	*1.3 NM to RW10L	↑	↙	⬡
GP 3.00° TCH 50	101°	*1660	RW10L		* LNAV only.		
		3.3 NM	2 NM	1.2 NM	1.3 NM		
CATEGORY	A	B	C	D			
LPV DA #		1015/24	200 (200-½)				
LNAV/VNAV DA		1197/35	382 (400-⅝)				
LNAV MDA	1280/24	465 (500-½)	1280/50	465 (500-1)			
CIRCLING	1340-1	525 (600-1)	1520-2 705 (800-2)	1520-2¼ 705 (800-2¼)			

