

CINCINNATI MUNI/LUNKEN FLD (LUK)(KLUK) 3 SE UTC-5(-4DT) N39°06.18' W84°25.06'

CINCINNATI
H-10G, L-27E
IAP, AD

482 B LRA Class IV, ARFF Index A NOTAM FILE LUK
RWY 03-21: H6101X150 (ASPH-GRVD) S-60, D-70, 2D-140
PCN 42 R/C/X/T HIRL

RWY 03: REIL. PAPI(P4R)—GA 3.0° TCH 44'. RVR-R Tree.
RWY 21: MALS. PAPI(P4L)—GA 3.0° TCH 39'. RVR-T Trees.
RWY 07-25: H5127X100 (ASPH-GRVD) S-11, D-20, 2D-55
PCN 38 R/C/X/T MIRL
RWY 07: Thld dspclcd 439'. Tree.
RWY 25: VASI(V4L)—GA 3.0° TCH 40'.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 03: TORA-6101 TODA-6101 ASDA-6101 LDA-6101
RWY 21: TORA-6101 TODA-6101 ASDA-6101 LDA-6101
SERVICE: S4 FUEL 100LL, JET A+ OX1 LGT When ATCT clsd actv
or incr instst MALS. Rwy 21; HIRL Rwy 03-21—CTAF. HIRL Rwy
03-21 preset on med instst. Rwy 07-25 PCL unavbl. Rwy 03 PAPI
unusbl byd 7 degs left of cntrln. Rotating bcn located 1.7 NM E of
arprt.

NOISE: Noise abatement procs in efct call amgr. Acft maint runups rstrd
btm 0200-1200Z†.

AIRPORT REMARKS: Attended continuously. Deer and birds on and invof
arprt. Fuel A+ C513-871-2020. Clsd scheduled ACR ops greater
than 9 pax seats. 48 hr PPR for unsched ACR ops with gtr than 30 passenger seats call amgr. Rwy 07-25 clsd to unsked
acr ops gtr than 30 pax seats. AER Rwy 25 and Rwy 21 are closely lctd; vfy cor rwy with compass hdg bfr dep. Arprt sfc
cond unmon dly 0400-1200Z†. Twy D, E, G, & H clsd to unsked acr ops gtr than 30 pax seats. Twy H not vsb fm ATCT,
ctc ground control. When ATCT clsd, use CTAF. Ldg fee. Flight Notification Service (ADCUS) available.

AIRPORT MANAGER: 513-352-6340

WEATHER DATA SOURCES: ASOS (513) 321-6291

COMMUNICATIONS: CTAF 118.7 ATIS 123.6 UNICOM 122.95

® APP/DEP CON 121.0

LUNKEN TOWER 118.7 (1200-0400Z†) GND CON/CLNC DEL 121.9 CLNC DEL 124.9 (when twr closed)

AIRSPACE: CLASS D svc 1200-0400Z†; other times CLASS E.


VOR TEST FACILITY (VOT) 108.4

RADIO AIDS TO NAVIGATION: NOTAM FILE CVG.

(L) (L) VORTACW 117.3 CVG Chan 120 N39°00.96' W84°42.20' 073° 14.3 NM to fld. 878/4W.

ILS/DME 110.9 I-LUK Chan 46 Rwy 21. Class IA. Unmonitored when ATCT clsd. DME unusable byd 25° left of
course.

COMM/NAV/WEATHER REMARKS: Emerg frequency 121.5 not avbl at twr. Cust in tempo fac; cust fac reqs must be smtd to arprt
first by calling 513-709-2761 or email #DOTE-AVIATION@CINCINNATI.OH.GOV.



CINCINNATI WEST (See HARRISON on page 290)

CINCINNATI/NORTHERN KENTUCKY INTL (See COVINGTON on page 278)

CIRCLEVILLE

PICKAWAY CO MEML (CYO)(KCYO) 5 S UTC-5(-4DT) N39°30.96' W82°58.93'

CINCINNATI
L-29A
IAP

685 B NOTAM FILE DAY

RWY 01-19: H4346X75 (ASPH) S-30, D-40 MIRL 0.5% up N

RWY 01: Trees.

RWY 19: REIL. PAPI(P4R)—GA 3.0° TCH 24'.

SERVICE: FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 19; PAPI Rwy 19; MIRL—CTAF.

AIRPORT REMARKS: Unatndd. Fuel: 100LL and Jet A avbl H24 via credit card.

AIRPORT MANAGER: 740-474-5145

COMMUNICATIONS: CTAF/UNICOM 122.7

® COLUMBUS APP/DEP CON 134.0

CLEARANCE DELIVERY PHONE: For CD ctc Columbus Apch at 614-338-8537.

RADIO AIDS TO NAVIGATION: NOTAM FILE DAY.

APPLETON (VH) (H) VORTAC 116.7 APE Chan 114 N40°09.06' W82°35.30' 212° 42.2 NM to fld. 1354/6W.

VOR unusable:

025°-030°

TACAN AZIMUTH unusable:

075°-095°

110°-115°

DME unusable:

075°-080°

YELLOW BUD (T) VORW 112.5 XUB N39°31.61' W82°58.68' at fld. 689/5W.