
TOLEDO MUNI (8C5) 2 E UTC-6(-5DT) N41°59.29' W92°32.88' CHICAGO
 960 TPA—1760(800) NOTAM FILE FOD
RWY 17-35: 1850X100 (TURF)
RWY 17: Tree.
RWY 35: Thld dsplcd 395'. Pole.
AIRPORT REMARKS: Unattended. Arpt CLOSED SS-SR. Rwy 35 marked with yellow cones, dsplcd thresholds marked with 3 yellow cones each side. Ctn - Line of sight ltd btn rwy ends due to rwy grade. 175' X 25' asph strip at the apch end of Rwy 17 used as twy.
AIRPORT MANAGER: 641-484-2741
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.

TOMMI N42°27.61' W96°27.73' NOTAM FILE SUX. OMAHA
 NDB (MHW/LOM) 305 Ol at Martin Fld. 1104/3E. NDB unmonitored when SUX ATCT clsd. L-121
 NDB unusable:
 140°-155° byd 10 NM

TRAEER MUNI (8C6) 1 NE UTC-6(-5DT) N42°12.05' W92°27.40' CHICAGO
 892 NOTAM FILE FOD
RWY 17-35: 2555X100 (TURF) LIRL 0.3% up S
RWY 17: Trees.
RWY 35: Tree. Rgt tfc.
AIRPORT REMARKS: Unattended. MOGAS and 100LL fuel avbl for emerg only, call 319-476-4353. Snow removal delayed at times; confirm rwy condition prior to use call 319-478-2580. Turf rwy soft during spring thaw. Rwy 17-35 marked with yellow cones.
AIRPORT MANAGER: (319) 478-2580
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.
