

RICHLANDS

TAZEWELL CO (JFZ)(KJFZ) 2 S UTC-5(-4DT) N37°03.82' W81°47.90'

2653 B NOTAM FILE JFZ

RWY 07-25: H4299X75 (ASP) S-12.5, D-18 MRL

RWY 07: REIL. PAPI(P2L)—GA 3.5° TCH 47'. Trees.

RWY 25: REIL. PAPI(P2L)—GA 3.5° TCH 47'. Tree.

SERVICE: FUEL 100LL, JET A+ LGT MRL Rwy 07-25 preset low instst.

To increase instst and ACTVT REIL Rwy 07 and 25; PAPI Rwy 07-25—CTAF.

AIRPORT REMARKS: Attended Mon-Sat 1300-2200Z†. Unattended New Year's Day, Thanksgiving, and Christmas. For Sunday svc call arpt during regular business hrs to arrange. Rwy 07 markings covered by algae. Rwy 25 markings covered by algae.

AIRPORT MANAGER: 276-963-4509

WEATHER DATA SOURCES: AWOS-3 118.075 (276) 596-9927.

COMMUNICATIONS: CTAF/UNICOM 123.05

Ⓡ ATLANTA CENTER APP/DEP CON 127.85

GCO 135.075 (thru ZTL clnc del and DCA RADIO) - inop.

CLEARANCE DELIVERY PHONE: For CD if una via GCO ctc Atlanta ARTCC at 770-210-7692.

RADIO AIDS TO NAVIGATION: NOTAM FILE DCA.

GLADE SPRING (L) (L) VOR/DME 115.55 GZG Chan 102(Y)

N36°49.51' W82°04.74' 045° 19.7 NM to fld. 4200/2W.

VOR unusable:

010°-095°

115°-120° byd 20 NM blo 10,000'


351°-004° byd 15 NM blo 8,000'

LOC/DME 109.75 I-JFZ Chan 34(Y) Rwy 25.

CINCINNATI

L-26H

IAP



RICHMOND

RICHMOND EXEC/CHESTERFIELD CO (FCI)(KFCI) 4 SW UTC-5(-4DT) N37°24.39'

W77°31.49'

236 B TPA—See Remarks LRA NOTAM FILE DCA

RWY 15-33: H5500X100 (ASP-GRVD) S-60, D-80 HIRL

0.7% up NW

RWY 15: REIL. PAPI(P4L)—GA 3.0° TCH 43'. Trees.

RWY 33: MALSR. PAPI(P4L)—GA 3.0° TCH 50'. Brush.

SERVICE: S4 FUEL 100LL, JET A OX3 LGT HIRL Rwy 15-33 preset

low instst; incr instst and actvt MALSR Rwy 33 and REIL Rwy 15—CTAF.

NOISE: Noise sensitive area north of arpt. No wind voluntary use of Rwy 15 preferred.

AIRPORT REMARKS: Attended 1200-0300Z†. Fuel aft hrs call

804-271-7793 or 844-435-9732 btn 0300-1200Z†. 400' twr 5

NM north of arpt. Act on ILS apch to Richmond Intl crossing over arpt.

Med-flight: irregular departure pattern. Helicopter parking adj to Twy C.

TPA—1236(1000) single engine, 1736(1500) multi-engine. ARFF

eqpt and trained personnel avbl at arpt.

AIRPORT MANAGER: 804-768-7722

WEATHER DATA SOURCES: AWOS-3PT 128.625 (804) 271-8426.

COMMUNICATIONS: CTAF/UNICOM 123.05

Ⓡ POTOMAC APP/DEP CON 126.75 118.2

CLNC DEL 124.6

CLEARANCE DELIVERY PHONE: For CD ctc Potomac Apch at 866-640-4124.

RADIO AIDS TO NAVIGATION: NOTAM FILE DCA.

FLAT ROCK (H) (H) VORTAC 113.3 FAK Chan 80 N37°31.71' W77°49.69' 123° 16.2 NM to fld. 460/6W.

TACAN 338 radial unusable

VOR unusable:

111°-168°

169°-204° blo 5,000'

274°-337° blo 4,000'

274°-337° byd 33 NM

ILS/DME 108.3 I-CFU Chan 20 Rwy 33. Class IA. LOC/DME unmonitored when arpt unatndd.

WASHINGTON

H-10H, 12I, L-36H

IAP

