NAPLES	
BRANDY POND SPB (5ME) 1 SE UTC-5(-4DT) N43°57.23´W70°35.25´	NEW YOR
268 NOTAM FILE BGR Waterway 17W-35W: 7200X600 (Water) Service: S2 fuel mogas	
SEAPLANE REMARKS: Attended May–Oct Mon–Fri 1300–2200Z <sup>‡</sup> , Nov–Apr unattended. Follow channel markers to a shallow water, turn west after 3rd marker to dock. Jun–Aug heavy boat tfc on lake.	
AIRPORT MANAGER: (207) 693-6254	
COMMUNICATIONS: CTAF 122.9	
CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 207-874-7320, when Apch clsd ctc Boston ARTCC at 603-879-6859.	
LONG LAKE SPB (76B) 1 NE UTC-5(-4DT) N43°59.22′ W70°37.11′ 268 NOTAM FILE BOR	NEW YOR
WATERWAY 16W-34W: 15000X3960 (WATER)	
SERVICE: FUEL 1001	
SEAPLANE REMARKS: Attended Jun-Oct 1400Z‡-dusk. June-Oct Sun unatndd. 100LL emerg fuel only. Wind so	ick at dock.
AIRPORT MANAGER: 207-232-2594	
COMMUNICATIONS: CTAF 122.9	
CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 207-874-7320, when Apch clsd ctc Boston ARTCC a 603-879-6859.	at
COMM/NAV/WEATHER REMARKS: Monitor CTAF within 5 NM of Naples.	
NEWTON FLD (See JACKMAN on page 73)	
NORCROSS(MILLINOCKET)	
	HALIFA
BUCKHORN CAMPS SPB (78B) O NE UTC-5(-4DT) N45°39.25' W68°56.97' 500 NOTAM FILE BGR	TALIFA
500 NOTAM FILE BGR	

500 NOTAM FILE BGR WATERWAY N=SE: 4000X500 (WATER) WATERWAY SE: Trees. WATERWAY SE: Trees. WATERWAY E: Trees. WATERWAY W: Trees. SEAPLANE REMARKS: Attended continuously. Many shallow rocky areas during low water conditions in middle of lake. Many shallow rocky areas around the docking area. Shallow areas with rocks near island west of the NW/SE sea lane. AIRPORT MANAGER: 207-723-1548 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.