

CONNER

WEST FORK LODGE (4U7) 5 SW UTC-7(-6DT) N45°51.74' W114°13.07'

GREAT FALLS

4249 NOTAM FILE GTF

RWY 02-20: 2600X65 (TURF-GRVL) 0.7% up S

RWY 02: Tree.

RWY 20: Road.

AIRPORT REMARKS: Unattended. Livestock, birds and wildlife invof arpt. No sn plowing in winter. Rwy 02-20 ocnl grvl down cntr of rwy-sml dip 600 ft fm Rwy 20 end. Steep terrain surrounding arpt. Trees and structures in transitional sfc full length both sides of ry. Rwy 02 +35 ft trees 600 ft fm rwy end and mt 2700 ft fm thr; Rwy 20 +135 ft tree 80 ft R and 120 ft fm rwy end; +115 ft trees bgn 91 ft R penetrating apch sfc.

AIRPORT MANAGER: (831) 884-3602

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

CONRAD (SØ1) 1 W UTC-7(-6DT) N48°10.10' W111°58.59'

GREAT FALLS

3548 B NOTAM FILE GTF

L-13C

RWY 06-24: H4602X75 (ASPH) S-12.5 MIRL 0.4% up SW

IAP

RWY 06: PAPI(P2L)—GA 3.0° TCH 45'. P-line.

RWY 24: REIL. PAPI(P2L)—GA 3.0° TCH 27'.

RWY 15-33: 2800X100 (TURF) 0.4% up SE

SERVICE: FUEL 100LL LGT ACTVT REIL Rwy 24; PAPI Rwy 24; MIRL Rwy 06-24—CTAF.

AIRPORT REMARKS: Unattended. 100LL 24/7 self svc. Twys have reflectors.

Rwy 06-24 has uneven sfc, cracks and rprs. Resurfacing sked 2024.

Rwy 06 faded and flaking paint. Rwy 24 faded and flaking paint.

AIRPORT MANAGER: (406) 450-1620

COMMUNICATIONS: CTAF/AUNICOM 122.8

CUT BANK RCO 122.2 (GREAT FALLS RADIO)

Ⓡ **SALT LAKE CENTER APP/DEP CON** 133.4

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

RADIO AIDS TO NAVIGATION: NOTAM FILE CTB.

CUT BANK (VL) (DH) VORW/DME 113.35 CTB Chan 80(Y)

N48°33.90' W112°20.60' 131° 28.0 NM to fld.
3791/17E.

VOR unusable:

- 049°-053° byd 40 NM
- 061°-073° byd 40 NM
- 079°-090° byd 40 NM
- 125°-130° byd 40 NM
- 143°-149° byd 40 NM
- 167°-177° byd 40 NM blo 9,000'
- 167°-177° byd 54 NM
- 178°-190° byd 40 NM
- 191°-201° byd 40 NM blo 12,000'
- 191°-201° byd 53 NM
- 202°-260° byd 40 NM
- 271°-282° byd 40 NM

