SEATTLE

SEATTLE

L-1E IAP

FLOATHAVEN SPB (See BELLINGHAM on page 224)

FLY FOR FUN (See VANCOUVER on page 284)

FORKS (S18) 1 SW UTC-8(-7DT) N47°56.26′ W124°23.76′

299 NOTAM FILE SEA

RWY 04-22: H2400X75 (ASPH) MIRL

RWY 04: Trees.

RWY 22: Tree. Rgt tfc.

AIRPORT REMARKS: Unattended. Wildlife on and invof arpt. Parallel twy marked with reflectors.

AIRPORT MANAGER: 360-374-5412

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

FRIDAY HARBOR

FRIDAY HARBOR (FHR)(KFHR) 0 SW UTC-8(-7DT) N48°31.32′ W123°01.46′ 113 R AOF NOTAM FILE FHR

.13 B AOE NOTAM FILE FHR

RWY 16–34: H3402X75 (ASPH–GRVD) S–12.5 MIRL 0.8% up N

RWY 16: REIL. PAPI(P2R)—GA 4.0° TCH 43'. Bldg. Rgt tfc.

RWY 34: REIL. PAPI(P4R)—GA 3.5° TCH 42′. Trees. Rgt tfc.

SERVICE: S4 FUEL 100LL LGT ACTVT REIL Rwy 16 and 34: PAPI Rwy

ERVICE: S4 FUEL 100LL LGT ACTVT REIL Rwy 16 and 34; PAPI Rwy 16 and 34; MIRL Rwy 16–34—CTAF. Rwy 16 PAPI UNUSBL byd 3 degs right of cntrln .

NOISE: NS ABTMT procedures in effect ctc arpt mgr 360–378–4724. For noise abatement avoid tkofs btn 0600–1500Z‡.

AIRPORT REMARKS: Attended Mon-Fri 1600–0100Z‡. No attendance during holidays. Bird activity on and invof arpt. Preferred Rwy 16 in calm wind conds. Due to high concentration of tfc invof arpt recommend Idg Igts or forward visibility Igts turned on while utilizing arpt. Acft with wingspan greater than 55′, 24 hr PPR, ctc arpt mgr 360–378–4724 or cell 360–317–8674. Tsnt turbine acft prkg less than 1 hr durn Ictd 250 ft S of trml ramp. Customs apron located on east side of terminal ramp. Soft ground btn tiedowns NE parking area. Acft in excess of 7,500 lbs charged fee based on wt ctc arpt mgr for info. Lndg fees charged for airlines and charters.

AIRPORT MANAGER: (360) 378-4724

WEATHER DATA SOURCES: ASOS 135.675 (360) 378-8491.

COMMUNICATIONS: CTAF 128.25

® WHIDBEY APP/DEP CON 118.2

CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.

RADIO AIDS TO NAVIGATION: NOTAM FILE BLL.

WHATCOM (H) (H) YORTACW 113.0 HUH Chan 77 N48°56.72′ W122°34.76′ 195° 31.0 NM to fld. 82/20E. TACAN AZIMUTH unusable:

155°-165° byd 15 NM blo 6,000′

NDB (MHW) 284 FHR N48°30.73′ W123°01.43′ at fld. 41/17E. NOTAM FILE FHR.

 ${\color{red}\textbf{COMM/NAV/WEATHER REMARKS:}}\ 128.25\ monitored\ intermittently.$

FRIDAY HARBOR SPB (W33) 0 NE UTC-8(-7DT) N48°32.24′ W123°00.58′

SEATTLE

00 AOE NOTAM FILE SEA WATERWAY 03W-21W: 10000X2000 (WATER)

WATERWAY 03W: Hill.

WATERWAY 19W 20W COOOVI OOO (MATER

WATERWAY 12W - Hill

WATERWAY 12W-30W: 6000X1000 (WATER)

WAIEKWAT 12W: HIII.

WATERWAY 30W: Hill.

SEAPLANE REMARKS: Unattended. All tkfs should be performed N of Browns Island. Flight Notification Service (ADCUS) available. General aviation overnight ldg fee.

AIRPORT MANAGER: (360) 378-4724 COMMUNICATIONS: CTAF 128.25

CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.

GOHEEN (See BATTLE GROUND on page 222)

03 C3 3/3 03 (C) æ C3 ^{C3} Ш agaaaa €3 €3 €3 G G 3402 X 75 C3 C3 C3 C3 €3 €3 G G 34 GG G €3 C3 C3