LANGLEY

WHIDBEY AIR PARK (W1Ø) 2 SW UTC-8(-7DT) N48°01.05′ W122°26.26′ SEATTLE

271 NOTAM FILE SEA RWY 16-34: H2470X25 (ASPH)

RWY 16: Trees

RWY 34: Tree.

AIRPORT REMARKS: Unattended. Wildlife invof rwy. Trees wi pri sfc.

AIRPORT MANAGER: (360) 321-0510

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle Apch at 206-214-4722.

LAURIER

AVEY FLD (69S) 2 SW UTC-8(-7DT) N48°59.90′ W118°13.36′ SFATTI F

1655 LRA NOTAM FILE SEA RWY 17-35: 1975X40 (GRVL)

RWY 17: Trees.

RWY 35: Trees

AIRPORT REMARKS: Unattended. Vehicles and animals on and invof rwy. Rwy 17 marked with retro-reflective devices. Bldg in pri sfc, slp both sides of rwy, and steep drop off at rwy ends. Helicopter operations on airport during fire season. Shoulders very soft and rough both sides of rwy. Canadian and U.S. customs avbl on hwy to the west. U.S. based acft should park on the U.S. side of ramp, south, and Canadian based acft should park on north side of ramp.

AIRPORT MANAGER: 509-631-0623 **COMMUNICATIONS: CTAF 122.9**

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

I EAVENWORTH

LAKE WENATCHEE STATE (27W) 14 NW UTC-8(-7DT) N47°49.16' W120°43.19' SEATTLE

1939 NOTAM FILE SEA

RWY 09-27: 2473X100 (TURF) 0.4% up W

RWY 09: Road

RWY 27: Road.

AIRPORT REMARKS: Unattended. CLOSED 1 Oct-1 Jun. Pedestrians, vehicles and animals on and invof rwy. Two windsocks, one at each rwy end. Ctc WA State Aviation Division 360-709-8015 or 1-800-552-0666 WA area for facility info prior to use. For acft accidents/incidents ctc WA state emergency operations center 800-258-5990. Rwy marked with reflectors dur dates arpt is open.

AIRPORT MANAGER: (360) 618-2477 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

LIND (ØSØ) 2 NE UTC-8(-7DT) N46°58.61′ W118°35.23′ SEATTLE L-13A

1507 B NOTAM FILE SEA RWY 05-23: H3197X50 (ASPH)

RWY 23: Hill.

LGT ACTIVATE HIRL Rwy 05-23-CTAF.

AIRPORT REMARKS: Unattended. East end of rwy has 800' by 50' dirt graded safety area. Rwy 05–23 markings faded.

AIRPORT MANAGER: 509-677-3241

COMMUNICATIONS: CTAF 122 9

CLEARANCE DELIVERY PHONE: For CD ctc Grant County Apch at 509-762-2842, when Apch clsd ctc Seattle ARTCC at 253-351-3694

RADIO AIDS TO NAVIGATION: NOTAM FILE MWH.

MOSES LAKE (VH) (DH) VORW/DME 115.0 MWH Chan 97 N47°12.65′ W119°19.01′ 097° 33.0 NM to fld.

1193/18E.

VOR unusable:

025°-040° byd 40 NM

055°-070° byd 40 NM

071°-081° byd 40 NM blo 28,000′

175°-198° byd 40 NM blo 6,000°

175°-198° byd 67 NM blo 10,000′

175°-198° byd 70 NM

200°-210° byd 40 NM

220°-230° byd 40 NM

240°-253° byd 40 NM blo 18,000′

254°-260° byd 40 NM

315°-345° byd 40 NM

LITTLE GOOSE LOCK AND DAM (See STARBUCK on page 281)