
GLENWOOD SPRINGS MUNI (GWS)(KGWS) 3 S UTC-7(-6DT) N39°30.36' W107°18.55'

DENVER
L-9E

5916 NOTAM FILE DEN

RWY 14-32: H3305X50 (ASPH) S-15 0.3% up NW

RWY 14: Trees.

RWY 32: PAPI(P2L)—GA 4.0° TCH 30'. Road.

SERVICE: S4 FUEL 100LL, JET A QX 3, 4

NOISE: Noise abatement: When wind and weather permit use Rwy 32 for arrival and Rwy 14 for departure. No touch and go ldgs.

AIRPORT REMARKS: Attended Mon-Fri 1500-0000Z±. Fuel avbl 24 hrs via self-serve credit card pump. Arpt Manager on call at 970-445-0965. FBO PH:970-945-3073. Gusty winds frequently in vicinity of arpt. Wildlife on and invof arpt.

Numerous +25' buildings; trees; equipment; tie downs approximately 150' from centerline—both sides of rwy full length.

Rwy 32 has 20' hangars and +30' antenna 200' left of centerline at thld. Paragliding ops vicinity 1 to 2 miles northwest of arpt up to 18,000' MSL. Automated super UNICOM. Click 3 times for arpt information.

AIRPORT MANAGER: 970-445-0965

COMMUNICATIONS: CTAF/AUNICOM 123.0

RCO 122.2 (DENVER RADIO)

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE DEN.

RED TABLE (VH) (DH) VORW/DME 113.0 DBL Chan 77 N39°26.36' W106°53.68' 270° 19.7 NM to fld.
11800/12E.

VOR unusable:

040°-056° byd 40 NM

057°-074° byd 40 NM blo 16,300'

057°-074° byd 65 NM

075°-100° byd 40 NM

115°-130° byd 40 NM

160°-200° byd 40 NM

COMM/NAV/WEATHER REMARKS: Automated UNICOM, 3 clicks adzy.
