

TRIDENT BASIN SPB (T44) 0 N UTC-9(-8DT) N57°46.85' W152°23.48'

KODIAK

00 NOTAM FILE ENA

WATERWAY 02W-20W: 4400X200 (WATER)

SERVICE: FUEL 100LL

SEAPLANE REMARKS: Attended continuously. Fuel avbl with credit card. Reef exposed at both ends of waterway on low tides.

Birds invof ldg basin. Boats occasionally use spb waterlane. Pilots arriving/departing Trident Basin must ctc Kodiak twr for tfc advisories and/or special VFR clearance. When twr clsd pilots will self announce on CTAF.

AIRPORT MANAGER: 907-486-8060

COMMUNICATIONS: CTAF 119.8 UNICOM 122.8

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

KOKHANOK (9K2)(PFKK) 2 SW UTC-9(-8DT) N59°26.00' W154°48.16'

KODIAK

115 B NOTAM FILE ILI

L-2J, 3D

RWY 07-25: 3300X75 (GRVL) MIRL

IAP

RWY 07: REIL. PAPI(P4L)—GA 3.0° TCH 20'. Brush.

RWY 25: REIL. PAPI(P4L)—GA 4.0° TCH 23'. Brush.

SERVICE: LGT ACTIVATE PAPI and REIL Rwys 07 and 25, MIRL Rwy 07-25, rotating bcn and windcone—CTAF.

AIRPORT REMARKS: Unattended. Rwy not monitored, visual inspection prior to use. Horses on or invof rwy. 30' unlit twr approximately 300' north of Rwy 07-25.

AIRPORT MANAGER: 907-571-1261

COMMUNICATIONS: CTAF 122.9

Ⓡ **ANCHORAGE CENTER APP/DEP CON** 118.8

RADIO AIDS TO NAVIGATION: NOTAM FILE AKN.

KING SALMON (H) (H) VORTACW 112.8 AKN Chan 75 N58°43.48' W156°45.14' 038° 73.9 NM to fld. 95/16E.

TACAN antenna offset 150' se

TACAN AZIMUTH unusable:

130°-140° byd 13 NM blo 4,000'


130°-140° byd 30 NM

332°-348° byd 19 NM blo 5,000'

DME unusable:

332°-348° byd 19 NM blo 5,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



KOLIGANEK (JZZ)(PAJZ) 1 E UTC-9(-8DT) N59°43.61' W157°15.62'

KODIAK

272 B NOTAM FILE JZZ

L-3C

RWY 09-27: 3300X75 (GRVL) MIRL 1.0% up E

IAP

RWY 09: PAPI(P4R)—GA 3.5° TCH 39'. Brush.

RWY 27: PAPI(P4L)—GA 3.5° TCH 27'. Brush.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 09: TORA-3300 TODA-3300 ASDA-3300 LDA-3300

RWY 27: TORA-3300 TODA-3300 ASDA-3300 LDA-3300

SERVICE: LGT ACTVT MIRL Rwy 09-27; PAPI Rwy 09 and 27—CTAF. Actvt rotg bcn—CTAF.

AIRPORT REMARKS: Unattended. Rwy cond unmnt; rcmd visual insp prior to use. Rwy 09-27 heaves and humps; rwy sloughing off into tundra. Rwy slopes down toward W end. Rwy 09 and 27 thr mkd with lgts.

AIRPORT MANAGER: 907-842-5511

WEATHER DATA SOURCES: AWOS-3P 118.525 (907) 596-3302. (WX CAM)

COMMUNICATIONS: CTAF 122.9

KEMUK MOUNTAIN RCO 122.55 (DILLINGHAM RADIO) Opr

1645-0845Z†, other times ctc Kenai FSS.

ANCHORAGE CENTER APP/DEP CON 282.35 132.75

RADIO AIDS TO NAVIGATION: NOTAM FILE DLG.

DILLINGHAM (H) (H) VOR/DME 116.4 DLG Chan 111 N58°59.65'

W158°33.13' 026° 59.3 NM to fld. 81/15E.

COMM/NAV/WEATHER REMARKS: For a LD call to Dillingham FSS dial 907-842-5275. For a toll free call to Kenai FSS dial 1-866-864-1737.

