104 INDIANA

MISHAWAKA PILOTS CLUB (3C1) 3 SW UTC-5(-4DT) N41°39.42′ W86°02.08′ CHICAGO

755 B NOTAM FILE HUF **RWY 12–30**: 3140X100 (TURF)

RWY 12: Thid dsplcd 690'. Trees. RWY 30: Thid dsplcd 520'. Trees.

RWY 03–21: H2243X40 (ASPH) I RWY 03: Thid dspicd 187'. Road. RWY 21: Thid dspicd 200'. Road.

AIRPORT REMARKS: Attended irregularly. Arpt bon OTS indefly. Rwy end 12: nstd gnd mkrs. Rwy end 30: nstd gnd mkrs.

AIRPORT MANAGER: (574) 675-7575 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc South Bend Apch 574-251-2609. When South Bend Apch clsd, for CD ctc Chicago ARTCC at 630-906-8921.

ST JOSEPH RIVER SPB (ØIN) 2 NE UTC-5(-4DT) N41°41.78′ W85°56.29′

CHICAGO

750 NOTAM FILE HUF

WATERWAY 10W-28W: 2675X100 (WATER)

SEAPLANE REMARKS: Unattended. Rwy 10W-28W: dep ctc KEKM tower at 119.5 bfr turning nbnd.

AIRPORT MANAGER: 317-232-0935 COMMUNICATIONS: CTAF 122.9

EMINENCE

PAM'S PLACE (78I) 3 SW UTC-5(-4DT) N39°30.10′ W86°41.31′

ST LOUIS

791 NOTAM FILE HUF

RWY 10-28: 3630X100 (TURF) 0.4% up E

RWY 10: Thid dsplcd 745'. Trees. RWY 28: Thid dsplcd 930'. Tree.

RWY 18-36: 1629X100 (TURF) 0.9% up S

RWY 18: Pole. RWY 36: Tree. SERVICE: S2

AIRPORT REMARKS: Attended irregularly. Deer and birds on and invof arpt. Rwy 10 edge mkd with grassline; dsplcd thr mkd with 3 traffic cones. Rwy 28 edge mkd with grassline; dsplcd thr mkd with 3 traffic cones. 24 hr emerg phone lctd in blue container on wall of SW bldg.

AIRPORT MANAGER: 217-274-1999
COMMUNICATIONS: CTAF 122.9

 $\textbf{CLEARANCE DELIVERY PHONE:} \ \text{For CD ctc Indianapolis Apch at } 317\text{-}227\text{-}5743.$