

BRODHEAD (C37) 2 S UTC-6(-5DT) N42°35.73' W89°22.88' CHICAGO
 792 TPA—1592(800) NOTAM FILE GRB
RWY 09-27: 2440X155 (TURF) LIRL(NSTD) 0.3% up W
RWY 09: Trees.
RWY 27: Trees.
RWY 03-21: 1500X100 (TURF) 0.3% up SW
RWY 03: Trees.
RWY 15-33: 1380X100 (TURF) 0.4% up SE
RWY 33: Trees.
SERVICE: S2 LGT ACTIVATE LIRL Rwy 09-27—CTAF. Rwy 09-27 NSTD LIRL spacing.
AIRPORT REMARKS: Unattended. Deer invof movement areas. Rwys not plowed in winter, open to ski acct. Irrigation equipment near movement areas. Rwy 03-21 mkd with red & white half barrels. Rwy 09-27 mkd with red & white half barrels. Rwy 33 marked with concrete pad. Crop dusting ops in area.
AIRPORT MANAGER: (608) 576-6645
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.

BROOKFIELD

CAPITOL DRIVE (Ø2C) 3 E UTC-6(-5DT) N43°05.38' W88°10.77' CHICAGO
L-28H, A
 844 B TPA—1644(800) NOTAM FILE GRB
RWY 09-27: 3387X100 (TURF)
RWY 09: Brush.
RWY 27: Trees.
RWY 03-21: H2994X45 (ASPH) MIRL 0.5% up SW
RWY 03: Thld dsplcd 1378'. Brush.
RWY 21: Thld dsplcd 694'. Brush.
RWY 18-36: 1602X80 (TURF) 0.9% up S
RWY 18: Tree.
RWY 36: Brush.
SERVICE: FUEL 100LL, MOGAS LGT ACTIVATE MIRL Rwy 03-21—CTAF.
AIRPORT REMARKS: Attended Apr-Oct 1400Z±-dusk, Nov-Mar 1400-0000Z±. Rwy 03 and Rwy 36 acct ops cannot see Rwy 27 acct ops. Rwy 09-27 and Rwy 18-36 opn for ski equipped acct Dec 1 thru Apr 15. Rwy 09-27 and Rwy 18-36 not snd or plwd. Cfm conds and sn removal for Rwy 03-21 with amgr 262-781-4213. Rwy 09-27 and Rwy 18-36 mkd with yellow cones. Rwy 03-21 markings faded.
AIRPORT MANAGER: 262-781-4213
COMMUNICATIONS: CTAF/UNICOM 122.7
CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.
RADIO AIDS TO NAVIGATION: NOTAM FILE MKE.
BADGER (H) (H) VORW/DME 116.4 BAE Chan 111 N43°07.01' W88°17.06' 107° 4.9 NM to fld. 1070/2E.

BURBUN N42°41.36' W88°18.11' NOTAM FILE BUU. CHICAGO
(T) DME 114.5 BUU Chan 92 at Burlington Muni. 772. L-28H, A

BURLINGTON MUNI (BUU)(KBUU) 1 NW UTC-6(-5DT) N42°41.44' W88°18.28' CHICAGO
L-28H, A
IAP
 780 B NOTAM FILE BUU
RWY 11-29: H4300X75 (ASPH) S-20 MIRL
RWY 11: REIL. PAPI(P2L)—GA 3.5° TCH 36'.
RWY 29: REIL. PAPI(P2L)—GA 3.25° TCH 46'. Rgt tfc.
RWY 01-19: 2410X130 (TURF)
RWY 19: Rgt tfc.
SERVICE: S4 FUEL 100LL, JET A OX4 LGT Actvt REIL Rwy 11 & 29; PAPI Rwy 11 & 29; MIRL Rwy 11-29—CTAF.
AIRPORT REMARKS: Attended 1400Z±-Dusk. Waterfowl on and invof arpt. Fuel 24 hr self svc. Tfc departing Rwy 11 avoid overflight of city. Departing tfc climb to 1000' AGL before turning south. Asp twy 30' wide, except W 700' 35' wide. Rwy 01-19 marked with yellow/black wooden panels.
AIRPORT MANAGER: 262-342-5003
WEATHER DATA SOURCES: AWOS-3 125.275 (262) 757-0907.
COMMUNICATIONS: CTAF/UNICOM 123.05
® MILWAUKEE APP/DEP CON 135.875
GCO 121.725 (FLIGHT SERVICES)
CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.
RADIO AIDS TO NAVIGATION: NOTAM FILE BUU.
BURBUN (T) DME 114.5 BUU Chan 92 N42°41.36' W88°18.11' at fld. 772.
BADGER (H) (H) VORW/DME 116.4 BAE Chan 111 N43°07.01' W88°17.06' 180° 25.6 NM to fld. 1070/2E. NOTAM FILE MKE.