

NEW RICHMOND RGNL (RNH)(KRNH) 2 N UTC-6(-5DT) N45°08.87' W92°32.35'**GREEN BAY**

998 B NOTAM FILE RNH

H-2J, L-14I, A

RWY 14-32: H5507X75 (ASPH) S-30, D-60 MIRL

IAP

RWY 14: REIL. PAPI(P4L)—GA 3.0° TCH 40' . Tree.**RWY 32:** REIL. PAPI(P4L)—GA 3.0° TCH 20' .**RWY 04-22:** 2050X75 (TURF)**SERVICE:** S4 **FUEL** 100LL, JET A **OX 4** **LGT** MIRL Rwy 14-32 preset on low inst; to incr inst and **ACTIVATE** REIL Rwys 14 and Rwy 32, PAPI Rwy 14 and Rwy 32—CTAF. Rwy 32 PAPI unusable byd 4° R of course.**AIRPORT REMARKS:** Attended continuously. 24 hr self fuel avbl for credit card users or call 715-246-5338. Seaplane tfc adjacent to south side of arpt. Deer and birds on and invof arpt. Aerobatic practice area 4NM northeast of arpt. Ultralight activity on and invof arpt. Turbo-jet touch and go not authorized. Bright lgts from ball fields 1/2 mile south during evenings May thru Sep. Rwy 04-22 marked with white cones. Open to ski equipped acft winter months. Automobile and pedestrian access onto arpt properly restricted by security fencing and gates from 0400-1200Z†. Contact arpt manager 715-246-7735 for access instructions.**AIRPORT MANAGER:** 715-246-7735**WEATHER DATA SOURCES:** AWOS-3 120.0 (715) 246-3202.**COMMUNICATIONS:** CTAF/UNICOM 122.975Ⓡ **MINNEAPOLIS APP/DEP CON** 121.2**GCO** 121.725 (MINNEAPOLIS APCH CTL)**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis Apch at 612-726-9086.**RADIO AIDS TO NAVIGATION:** NOTAM FILE PNM.**GOPHER (H) (H) VORTACW** 117.3 **GEP** Chan 120 N45°08.74' W93°22.39' 084° 35.4 NM to fld. 877/6E.**HELIPAD H1:** H40X40 (ASPH)**NORTH COUNTRY SPB** (See SOLON SPRINGS on page 386)**OCONTO/J DOUGLAS BAKE MUNI** (OCQ)(KOCQ) 2 SW UTC-6(-5DT) N44°52.44' W87°54.59'**GREEN BAY**

604 B NOTAM FILE GRB

L-31A

RWY 11-29: H3198X75 (ASPH) S-40, D-55, 2D-90 MIRL

IAP

RWY 11: REIL. PAPI(P2L)—GA 4.0° TCH 31' .**RWY 29:** REIL. PAPI(P2L)—GA 4.0° TCH 31' .**RWY 04-22:** 1840X150 (TURF)**SERVICE:** **FUEL** 100LL **LGT** Actvt REIL Rwy 11 & 29; MIRL Rwy 11-29—CTAF. Rwy 29 PAPI unusbl byd 8 degs right of cntrln.**AIRPORT REMARKS:** Attended Mon-Fri irregularly. Migratory waterfowl on & invof arpt. 24 hr fuel avbl with credit card. Confirm winter rwy conditions and snow removal with arpt manager 920-834-7727. Rwy 04-22 not plwd Nov-Apr. Rwy 04-22 mkd with white cones.**AIRPORT MANAGER:** 920-834-7727**WEATHER DATA SOURCES:** AWOS-3 120.925 (920) 835-1599.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **GREEN BAY APP/DEP CON** 120.3 (1130-0530Z† other times ctc)Ⓡ **MINNEAPOLIS APP/DEP CON** 124.4**CLEARANCE DELIVERY PHONE:** For CD ctc Green Bay Apch at 920-431-5741, when Green Bay Apch clsd, for CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE GRB.**GREEN BAY (VH) (H) VORTACW** 115.5 **GRB** Chan 102 N44°33.31' W88°11.69' 031° 22.7 NM to fld. 767/1E.

VOR unusable:

000°-025° byd 40 NM

026°-036° byd 40 NM blo 2,600'

026°-036° byd 49 NM

040°-047° byd 40 NM

048°-058° byd 40 NM blo 18,000'

059°-065° byd 40 NM

221°-233° byd 40 NM

255°-265° byd 40 NM

270°-300° blo 7,000'