

**NEW ULM MUNI** (ULM)(KULM) 2 W UTC-6(-5DT) N44°19.10' W94°30.10'

OMAHA

1011 B NOTAM FILE ULM

L-121

**RWY 15-33:** H5401X100 (ASPH-GRVD) MIRL

**RWY 15:** REIL. PAPI(P4L)—GA 3.0° TCH 25'.

**RWY 33:** MALSF. PAPI(P4R)—GA 3.0° TCH 50'.

**RWY 04-22:** 2478X160 (TURF)

**SERVICE:** S4 FUEL 100LL, JET A LGT ACTVT MALSF Rwy 33; REIL

Rwy 15; PAPI Rwy 15 and 33; MIRL Rwy 15-33—CTAF.

**AIRPORT REMARKS:** Attended Mon-Fri 1400-2300Z±. 100LL fuel avbl H24 via credit card. Rwy 04-22 clsd winter months. Rwy 04 mkd with yellow cones. Rwy 22 mkd with yellow cones.

**AIRPORT MANAGER:** 507-354-4337

**WEATHER DATA SOURCES:** AWOS-3 118.325 (507) 359-1656.

**COMMUNICATIONS:** CTAF/UNICOM 123.0

Ⓡ MINNEAPOLIS CENTER APP/DEP CON 127.1

GCO 121.725 (MINNEAPOLIS CENTER and FLIGHT SERVICES)

**CLEARANCE DELIVERY PHONE:** For CD if una via GCO ctc Minneapolis ARTCC at 651-463-5588.


**RADIO AIDS TO NAVIGATION:** NOTAM FILE MKT.

**MANKATO (L) DME** 110.8 MKT Chan 45 N44°13.19'

W93°54.74' 283° 26.1 NM to fld. 1026.

DME unusable:

325°-150° byd 16 NM



**NODINE** N43°54.74' W91°28.05' NOTAM FILE PNM.

CHICAGO

(H) (H) VORTACW 117.9 ODI Chan 126 249° 16.8 NM to Rushford Muni/Robert W Bunke Fld. 1282/1E.

H-21, L-28F

**NORMAN CO ADA/TWIN VALLEY** (See ADA/TWIN VALLEY on page 150)

**NORTHOME MUNI** (43Y) 2 NE UTC-6(-5DT) N47°53.28' W94°15.49'

TWIN CITIES

1430 B NOTAM FILE PNM

**RWY 12-30:** 3199X147 (TURF) LIRL(NSTD)

**RWY 02-20:** 2049X148 (TURF)

**RWY 02:** Trees.

**RWY 20:** Thld dspclcd 209'. Trees.

**SERVICE:** LGT Rwy 12-30 NSTD LIRL due to vrb spacing, nmrs rwy edge lgts inop.

**AIRPORT REMARKS:** Unattended. Rwy 02-20 not mntnd winter months. Rwy 02 marked with yellow cones. Rwy 20 rwy and dtlr mkd with yellow cones. Rwy 12-30 marked with yellow cones. Rwy 02 uneven surface near rwy end. Ruts in Rwy 12-30. Tiedowns not mkd.

**AIRPORT MANAGER:** 218-434-1743

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.