

MERCER CO RGNL (See HAZEN on page 344)

MILNOR MUNI (4R6) 1 E UTC-6(-5DT) N46°15.50' W97°26.27'

TWIN CITIES

1091 NOTAM FILE GFK

RWY 08-26: 2210X90 (TURF)

RWY 08: Road.

AIRPORT REMARKS: Unattended. Deer and birds on or invof arpt. Confirm arpt condition prior to ldg due to irregular snow removal, phone request only 701-680-1001. Rwy 08-26 crosswind turbulence due to close proximity tree growth, additionally, tress to north and south, windsocks and buildings to the north of rwy penetrate 7:1 transitional surface. Rwy 08-26 has 250' turf stopway west end.

AIRPORT MANAGER: 701-680-1001

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

MINOT AFB (MIB)(KMIB) AF 10 N UTC-6(-5DT) N48°24.95' W101°21.48'

BILLINGS

1666 B TPA—See Remarks NOTAM FILE MIB Not insp.

H-2H, L-14F

RWY 12-30: H13198X300 (ASPH-COMC-GRVD) PCN 70 R/B/W/T HIRL

DIAP, AD

RWY 12: ALSF1. PAPI(P4L)—GA 2.5° TCH 47'.

RWY 30: ALSF1. PAPI(P4L)—GA 2.5° TCH 49'. Rgt tfc.

SERVICE: S4 OX2 MILITARY—LGT Rot Bcn not vis fr E. JASU 9(MD-3A) 2(M32A-60A) (MA-1A) FUEL A++ FLUID SP PRESAIR De-Ice—Exp possible delay wkend. LOX LHOX LHNIT OIL O-133-148 JOAP - Rqr 2 hr PN wkend. **TRAN ALERT** Opr 1330-2330Z± wkd; clsd Sat and Sun. Fleet svc unavbl.

MILITARY REMARKS: Opr 1300-0500Z± Mon-Thu; 1300-0000Z± Fri; clsd Sat, Sun, AFGSC apv down days and federal hol exc by NOTAM. See FLIP AP/1 Supplementary Arpt Information. **RSTD** PPR ctc afld mgmt 72 hr pn DSN 453-2347, C701-723-2347. PPR all acct incl distinguished visitor, haz cargo and AIREVAC regardless of affiliation for notification and coord purposes. All ron tran crews must ctc Comd Post with billeting arng. All VIP acct ctc Comd Post no later than 60 NM out. Avoid overflight blo 4200' of airfield when clsd, excluding published instrument approach of departure procedure. All aircrews req PPR outside of publ afld hr ctc comd post. **CAUTION**—Bash phse II eff 01 Mar-31 May, 01 Sep-30 Nov. Bird haz. Uncontrolled vehicle tfc on twy. Uncontrolled helicopter ops outside of public operating hrs. High potential for hydroplaning first/last 3000' of rwy when rwy sfc condition present. **TFC PAT** TPA—Rectangular 2900(1233), multi-engine jet rgt tfc Rwy 30; overhead 3400(1733), rgt break Rwy 12. **MISC** Wx opr H24. DSN 453-6385, C701-723-6385. AN/FMQ-19 ASOS in use, augmented by human obsn when nec dur afld hr. Wx obsn vis rstd NE-SE due to bldg. RSC/RCR and active rwy not reported when afld clsd. Due to C5/B747 acct prk lctn aircrews can exp delays for fueling and pax loading. **RWY** Rwy 12-30 100' wide conc keel sfc in cntr with 100' wide asphalt either side.

AIRPORT MANAGER: 701-723-2644

WEATHER DATA SOURCES: ASOS AN/FMQ-19 owned by USAF.

COMMUNICATIONS: SFA: PTD 372.2 ATIS 278.8 (Opr during local flying.)

Ⓡ **APP CON** 118.15 119.6 363.8 Opr 1300-0500Z± Mon thru Sun, other times ctc Minneapolis Center 127.6 279.6.

Ⓡ **DEP CON** 119.6 259.1 Opr 1300-0500Z± Mon thru Sun, other times ctc

MINNEAPOLIS CENTER 127.6 279.6

TOWER 120.65 253.5 (Opr 1300-0500Z± Mon thru Sun, other times ctc Minneapolis Center 127.6 279.6. See FLIP AP/1 Supplementary Arpt Remark.) **GND CON** 134.0 275.8 **CLNC DEL** 326.2

COMD POST 321.0 (Call RAYMOND 12); (DSN 453-3101, C701-723-3101)

PMSV METRO 342.5 (H24 0600Z Mon thru 0400Z± Sat; clsd Sat, Sun and hol as dictated by lcl msn or dur fcst svr wx cond. 342.5 Remarks: no svc outside afld opr hr, ctc comd post.)

AIRSPACE: CLASS D svc 1200Z± Mon- 0400Z± Thurs, 1500-2300Z± Sat-Sun; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE MIB.

DEERING (H) TACAN Chan 96 MIB (114.9) N48°24.92' W101°21.97' at fld. 1654/7E.

No NOTAM MP: 1530-1730Z± Wed (1500/3+1)

TACAN AZ unusable:

294°-304° byd 13 NM blo 5,000'

294°-304° byd 21 NM

DME unusable:

294°-304° byd 13 NM blo 5,000'

294°-304° byd 21 NM

ILS 109.9 I-MJW Rwy 12. Class IT.

ILS 109.9 I-MIB Rwy 30. Class IB. Rwy 12 ILS unprotected.

Digital ASR No NOTAM MP: 0600-1200Z± Mon-Fri (1500/3+1).