

SOUTH BETHLEHEM

SOUTH ALBANY (4B0) 2 N UTC-5(-4DT) N42°33.64' W73°50.04'

NEW YORK
L-32G, 33B, 34I
IAP

196 NOTAM FILE BTV

RWY 01-19: H2853X60 (ASPH) LIRL 0.4% up N

RWY 01: RVR-T Thld dsplcd 150'. Fence.

RWY 19: RVR-R Thld dsplcd 124'. Road.

SERVICE: S4 FUEL 100LL, JET A LGT ACTVT LIRL Rwy 01-19 and windsock lgt—CTAF.

NOISE: Helicopter noise abatement procedures in effect. VFR dep maintain rwy hdg until reaching 500' AGL. Avoid arr and dep to/from the west.

AIRPORT REMARKS: Attended Nov-Mar 1300-2100Z±, Apr-Oct 1100-0200Z±. Birds on and in/ov arpt. Arpt clsd to acft over 12,500 lbs. +17' railroad across centerline 200' S of Rwy 01.

AIRPORT MANAGER: (518) 281-5430

COMMUNICATIONS: CTAF 122.9

Ⓡ ALBANY APP/DEP CON 118.05

CLEARANCE DELIVERY PHONE: For CD ctc Albany Apch at 518-862-2299.

RADIO AIDS TO NAVIGATION: NOTAM FILE BTV.

CAMBRIDGE (L) (L) VORW/DME 115.0 CAM Chan 97 N42°59.66' W73°20.64' 234° 33.8 NM to fld. 1490/14W.

DME unusable:

040°-130° blo 9,000'

VOR unusable:

128°-144°

161°-182°

195°-205°

SOUTHAMPTON HELIPORT (87N) 5 SE N40°50.78' W72°27.98'

NEW YORK
COPTER
L-33C, 34I
IAP

5 NOTAM FILE ISP

HELIPAD H1: H44X44 (ASPH)

NOISE: Noise sensitive area due to houses nearby. No idling or waiting on helipad permitted.

HELIPORT REMARKS: Attended continuously. Rwy H1; +4 FT stone wall 22 FT S; +15 FT road 25 FT S; +47 FT house 230 FT S. Rwy H1; +24' brush 65' SE; +31' AWOS twr 165' SE; +45' bldg 430' SE. Rwy H1; +52' bldg 550' SW. Ldg fee \$150 for less than 5,000 lbs max gross ldg weight and \$200 for greater than or equal to 5,000 lbs max gross ldg weight. Rwy H1 +3' concrete block, 53' NE of helipad. Rwy H1, +5' dune, 300' NW of helipad.

AIRPORT MANAGER: 631-283-0247

COMMUNICATIONS: CTAF 122.9

Ⓡ NEW YORK APP/DEP CON 125.975

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2449

RADIO AIDS TO NAVIGATION: NOTAM FILE HTO.

HAMPTON (H) (H) VORTAC 113.6 HTO Chan 83 N40°55.14'

W72°19.00' 250° 8.1 NM to fld. 22/13W.

DME unusable:

280°-325° byd 35 NM blo 1,700'

326°-355° byd 30 NM blo 2,000'

TACAN AZIMUTH unusable:

280°-325° byd 35 NM blo 1,700'

326°-355° byd 30 NM blo 2,000'

VOR unusable:

010°-240°

270°-332°



SPENCERPORT AIRPARK (D91) 2 S UTC-5(-4DT) N43°10.17' W77°49.10'

DETROIT

614 NOTAM FILE BUF

RWY E-W: 2450X90 (TURF)

RWY E: Trees.

RWY W: Trees.

AIRPORT REMARKS: Attended irregularly. Deer on and in/ov arpt. Rwy E-W soft in winter. For rwy conditions call 585-737-3018. +80' antenna 2270' distance, 10' S of cntrln.

AIRPORT MANAGER: (585) 737-3018

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland ARTCC at 440-774-0490.

SPRINGVILLE XNT N42°30.54' W78°39.52'/1418

DETROIT
L-30I, 31E

AWOS-3P 122.8 (716) 592-4400 XNT AWOS-3P is associated with Betrand Chafee Hospital heliport 2NK6.