

UTICA N43°01.59' W75°09.87' NOTAM FILE BUF.
 (L) **TACAN** 111.2 UCA Chan 49 319° 16.4 NM to Griffiss Intl. 1420/OW.
RCO 122.2 (BUFFALO RADIO)

NEW YORK
L-32G

WALLKILL

KOBELT (N45) 2 NE UTC-5(-4DT) N41°37.45' W74°08.50'
 420 B NOTAM FILE ISP

NEW YORK

RWY 03-21: H2864X50 (ASPH) S-13

RWY 03: Trees.

RWY 21: Trees.

AIRPORT REMARKS: Unattended. Arpt clsd to acct 13,500 lbs and over. Deer on and invof arpt. PJE at arpt 3.0 NM radius SFC-14,500'. Rwy 03 has access road 16' from thld both sides. Rwy center width of 30' in good condition, 10' width on both sides of centerline in poor condition with extensive cracks and vegetation. Rwy 03-21 slight depression in grass areas opposite south end of rwy. Rwy center 30' in fair condition, outside edges beyond this in poor condition. 18' wide parallel twy, stub connectors to rwy between ends in poor condition.

AIRPORT MANAGER: 914-548-3028

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2448.

WARWICK MUNI (N72) 3 NE UTC-5(-4DT) N41°17.26' W74°17.23'
 540 NOTAM FILE ISP

NEW YORK

RWY 08-26: 2250X80 (TURF)

RWY 08: Tree.

RWY 26: Tree.

RWY 03R-21L: H2150X28 (ASPH) LIRL(NSTD)

RWY 03R: Tree.

RWY 21L: Trees.

RWY 03L-21R: 2100X50 (TURF)

RWY 03L: Trees.

RWY 21R: Trees.

SERVICE: FUEL 100LL LGT ACTIVATE LIRL Rwy 03R-21L-CTAF.

AIRPORT REMARKS: Attended irregularly. Arpt CLOSED to tran acct sunset-sunrise. Deer and bird act near movement areas. Mountains and twrs in close vicinity of arpt. Self svc fuel avbl. Rwy 08 has 6' chain link fence 58' left, parallel to rwy. Practice ldrs NA. Rwy 03R-21L NSTD LIRL, spacing 400' apart. Seaplane use of Wickham Lake prohibited.

AIRPORT MANAGER: 845-258-0183

COMMUNICATIONS: CTAF/UNICOM 123.0

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2448.