## OREGON

-

OWYHEE RESERVOIR STATE (28U) 2680 NOTAM FILE MMV RWY 13–31: 1840X30 (DIRT) RWY 13: Trees. AIRPORT REMARKS: Unattended. Owner arpt, no ground access. Arpt in car irregular maintenance. Rwy surfac AIRPORT MANAGER: 503-378-4880 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc	advises ctc nyon, surrou e frequently	nded by high ter rough and rutte	artment of Aviation 50 rain. 4 ′ brush growth d. Sur conds not rprtd	03–378–4880 prior within 20′ of rwy e	
PACIFIC CITY STATE (PFC)(KPFC) 10 NOTAM FILE MMV RWY 14-32: H1860X30 (ASPH) S-7 RWY 14: Tree. AIRPORT REMARKS: Unattended. Owner under water dur winter high tides. recommended and may not be pos cond. Assorted trees and 40' p-lir only. AIRPORT MANAGER: 503-378-4880 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc	advises ctc Ocnl driftwo ssible. Many ne at 500 ´ r	with Departme ood on rwy due close in obst or north of rwy. Pre	to flooding. Sfc conds both sides of rwy. Exp -tkof engine run-ups t	'8–4880 prior to us not rprtd. Downwir p low level turbulen	nd Idgs not ce dur crosswind
PAISLEY (22S) 3 NW UTC-8(-7) 4395 B NOTAM FILE MMV RWY 13-31: H4300X60 (ASPH) L AIRPORT REMARKS: Unattended. Rwy 1 AIRPORT MANAGER: 541-947-4222 COMMUNICATIONS: CTAF 122.9	IRL 0.4%		)°33.77′		KLAMATH FALLS L—11A

LAKEVIEW (H) (H) VORTACW 112.0 LKV Chan 57 N42°29.57′ W120°30.43′ 331° 13.7 NM to fld. 7465/19E.