OREGON 199

PINEHURST STATE (24S) 1 SW UTC-8(-7DT) N42°06.61′ W122°22.99′

3643 NOTAM FILE MMV

RWY 04-22: H2800X30 (ASPH) 2.0% up SW

RWY 04. Trees

RWY 22: Trees.

AIRPORT REMARKS: Unattended. Surface conditions not reported. Irregular winter maintenance. Arpt may be clsd by snow. Strong winds from any direction will likely cause low-level turbulence. Rwy 04-22 12 ft trees wi 25 feet of cntrln full len. Rwy 22 slopes up to the SW, with abrupt 4% rise on SW half of rwy. Owner advises contact Oregon Dept. of Aviation 503-378-4880 prior to use.

AIRPORT MANAGER: 503-378-4880 **COMMUNICATIONS: CTAF 122.9**

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

PITTSBURG LANDING (See IMNAHA on page 178)

PORTLAND

PORTLAND DOWNTOWN HELIPORT (61J) 0 N UTC-8(-7DT) N45°31.52′ W122°40.26′

SEATTLE

KLAMATH FALLS

78 B NOTAM FILE MMV

HELIPAD H1: 80X80 (ROOF-TOP) S-25 PERIMETER LGTS

SERVICE: LGT For heliport PLASI when approaching flt apch and tkf 020-activate CTAF 3 times. When approaching flt apch and tkf 025-activate CTAF 5 times. When approaching flt apch and tkf 030-activate CTAF 7 times.

HELIPORT REMARKS: Unattended. +199' radio twr (Igtd) 4950' E of heliport in flt apch and tkf 025°. Helipad H1 yellow perimeter lgts, blue centerline twy lgts to helipads. Helipad H1 single heliport with 4 flt apchs 162°/220°/248°/295°/ and tkf directions $342^{\circ}/040^{\circ}/068^{\circ}/115^{\circ}$. Arrow lgts for flt apch $220^{\circ}/248^{\circ}/295^{\circ}$ and tkf $040^{\circ}/068^{\circ}/115^{\circ}$. Ldg fee.

AIRPORT MANAGER: 503-823-6677 COMMUNICATIONS: CTAF/UNICOM 123.075

CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 503-493-7545.