

SCAPPOOSE (SPB)(KSPB) 1 NE UTC-8(-7DT) N45°46.26' W122°51.71'
 58 B NOTAM FILE SPB
RWY 15-33: H5100X100 (ASPH) S-30, D-50, 2D-90 MIRL

SEATTLE
 H-1B,L-1C
 IAP

0.6% up NW
RWY 15: REIL. PAPI(P4L)—GA 3.73° TCH 41'. Tree.
RWY 33: PAPI(P4L)—GA 3.0° TCH 40'. Rgt tfc.
SERVICE: S4 FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 15, PAPI Rwy 15 and Rwy 33, MIRL Rwy 15-33—CTAF. 7 clicks to ACTIVATE REIL.

AIRPORT REMARKS: Attended 1600Z†-dusk. Extv ultralight activity on west side parallel twy. Rwy 33 has basic markings plus aiming points. Blue lgts and cntrln reflectors at east side twy exits fm rwy. Twy B has med intensity twy lights. Rwy 15 is calm wnd rwy.

AIRPORT MANAGER: 503-397-2888
WEATHER DATA SOURCES: ASOS 135.875 (503) 543-6401.
COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ PORTLAND APP CON 124.35
 Ⓡ PORTLAND DEP CON 133.0

CLNC DEL 121.65
CLEARANCE DELIVERY PHONE: For CD ctc Portland approach at 503-493-7545.

RADIO AIDS TO NAVIGATION: NOTAM FILE PDX.


BATTLE GROUND (VH) (H) VORTACW 116.6 BTG Chan 113 N45°44.87' W122°35.49' 256° 11.4 NM to fld. 253/21E.

TACAN AZIMUTH unusable:
 035°-085° byd 35 NM blo 10,000'

DME unusable:
 035°-085° byd 35 NM blo 10,000'

VOR unusable:
 034°-044° byd 40 NM blo 14,500'
 034°-044° byd 56 NM
 045°-048° byd 40 NM
 049°-059° byd 40 NM blo 10,000'
 049°-059° byd 51 NM blo 11,500'
 049°-059° byd 59 NM
 060°-063° byd 40 NM
 064°-086° byd 40 NM blo 18,000'
 064°-086° byd 65 NM blo 22,000'
 092°-102° byd 40 NM blo 29,000'
 103°-109° byd 40 NM
 110°-120° byd 40 NM blo 18,000'
 121°-139° byd 40 NM blo 18,000'
 140°-145° byd 40 NM
 170°-180° byd 40 NM blo 5,000'
 170°-180° byd 49 NM
 181°-195° byd 40 NM
 196°-206° byd 40 NM blo 18,000'
 207°-285° byd 40 NM
 305°-323° byd 40 NM
 324°-334° byd 40 NM blo 5,000'
 324°-334° byd 47 NM
 335°-339° byd 40 NM
 340°-350° byd 40 NM blo 9,000'
 340°-350° byd 56 NM
 351°-027° byd 40 NM

LOC/DME 111.1 I-FKO Chan 48 Rwy 15. LOC unusable byd 20° w of course.



SEASIDE MUNI (56S) 1 NE UTC-8(-7DT) N46°00.90' W123°54.46'
 12 B NOTAM FILE MMV
RWY 16-34: H2211X50 (ASPH) S-12 MIRL

SEATTLE

RWY 16: Thld dsplcd 155'. Brush.
RWY 34: Road.
SERVICE: LGT ACTIVATE MIRL Rwy 16-34—CTAF.

AIRPORT REMARKS: Unattended. Birds and elk on and invof rwy.
AIRPORT MANAGER: 503-717-2896
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.