

---

**LOWER LOON CREEK** (C53) 30 SW UTC-7(-6DT) N44°48.52' W114°48.52' **GREAT FALLS**  
 4200 NOTAM FILE BOI  
**RWY 16-34:** 1200X25 (TURF-DIRT) 1.2% up S  
**RWY 16:** Tree.  
**RWY 34:** Brush.  
**AIRPORT REMARKS:** Unattended. Recommend land Rwy 16, dep Rwy 34 when wind cond allow. No winter maint. Rwy not marked. Arpt lctd on a plateau 50' to 75' abv the river. Lctd in narrow winding river canyon. Rodent activity adj both sides of rwy. Stock and big game animals invof rwy.  
**AIRPORT MANAGER:** 208-756-2271  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.

---

**MARBLE CREEK** (ID8) 36 WNW UTC-7(-6DT) N44°46.41' W114°59.12' **GREAT FALLS**  
 4685 NOTAM FILE BOI  
**RWY 04-22:** 1160X20 (DIRT-TURF)  
**RWY 04:** Hill.  
**RWY 22:** Trees.  
**AIRPORT REMARKS:** No winter maint. Use at own risk; rwy is very shrt and very challenging. Rwy is not mkd. Trees & trrn on apch to both rwy ends. Big game animals & stock on and in vcntry of rwy. Rwy is a very shrt & challenging strip due to hrg trrn & trees; rcmd for use only by experienced & properly trnd backcounty pilots with the right eqpt suitable for this environment. Due to hi density alt, ery mrrng & late eve ops is rcmd durg summer months. Apt lctd in dp canyon and is srmd by hi, timbered, mtous trrn. Rwy end 04 sfc cond is dominated by soft sandy soil for the first 350 ft—400 ft.  
**AIRPORT MANAGER:** 208-756-2271  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 1-801-320-2568.

---

**UPPER LOON CREEK USFS** (U72) 26 NW UTC-7(-6DT) N44°35.49' W114°49.39' **GREAT FALLS**  
 5500 NOTAM FILE BOI  
**RWY 04-22:** 2500X75 (TURF-DIRT)  
**RWY 04:** Tree.  
**RWY 22:** Trees.  
**AIRPORT REMARKS:** Unattended. Recommend land Rwy 22, tkf Rwy 04 when wind cond permit. Trees and high terrain on both ends of Rwy 04-22, requires a steep approach. Rwy 04-22 numerous additional obstructions on apch to both rwy ends. No winter maint. Recommended for experienced mountain pilots only. Rwy 04-22 edges and thlds marked with white rocks.  
**AIRPORT MANAGER:** 208-879-4101  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.

---

## CHAMBERLAIN GUARD STATION

**CHAMBERLAIN USFS** (U79) 0 E UTC-7(-6DT) N45°22.74' W115°11.81' **GREAT FALLS**  
 5765 NOTAM FILE BOI  
**RWY 07-25:** 4100X200 (TURF-DIRT)  
**RWY 07:** Trees.  
**RWY 25:** Tree.  
**RWY 15-33:** 2700X140 (TURF)  
**RWY 15:** Trees.  
**RWY 33:** Trees.  
**AIRPORT REMARKS:** Unattended. Rwy end 25—first 300 ft of sfc area bit rough. Rwy 15-33 rough and uneven sfc. Arpt subject to tmpry closure early spring due to soft rwys. Rwy 07-25 and Rwy 15-33 thrs mkd and rwys outlined with yellow rocks—barely vsb. Rwy 15-33 has +2' pipe and -2' ditch across rwy North of Rwy 07-25 int; first 300' of Rwy 33 clsd. +70 foot trees adjacent to all ry edges. Extv rodent activity on both rwys. No telephone avbl at arpt. Private Stone Breaker Arpt lctd 1 NM NE of Chamberlain USFS.  
**AIRPORT MANAGER:** 208-634-0600  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.

---

**CHAMBERLAIN USFS** (See CHAMBERLAIN GUARD STATION on page 45)

---