

**BAMBERG CO** (99N) 5 W UTC-5(-4DT) N33°18.27' W81°06.51'  
231 B NOTAM FILE AND

**CHARLOTTE**  
L-241  
IAP

**RWY 05-23:** H3603X60 (ASPH) S-30, D-60 MIRL 0.6% up NE

**RWY 05:** PAPI(P2L)—GA 3.0° TCH 40'. Tree.

**RWY 23:** PAPI(P2L)—GA 3.0° TCH 41'. Tree.

**SERVICE:** FUEL 100LL LGT Actvt PAPI Rwy 05 & 23; MIRL Rwy  
05-23—CTAF.

**AIRPORT REMARKS:** Unattended.

**AIRPORT MANAGER:** 803-245-5191

**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓡ **COLUMBIA APP/DEP CON** 124.15

**CLEARANCE DELIVERY PHONE:** For CD ctc Columbia Apch at 803-822-5242 or  
803-822-5040.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE AND.

**ALLENDALE (VL) VOR** 116.7 ALD N33°00.75'  
W81°17.53' 029° 19.8 NM to fld. 187/1W.

VOR unusable:

019°-029° byd 40 NM blo 3,000'  
019°-029° byd 52 NM  
030°-084° byd 16 NM blo 6,000'  
030°-084° byd 26 NM  
085°-109° byd 40 NM  
110°-120° byd 40 NM blo 6,000'  
110°-120° byd 48 NM  
110°-200° blo 3,000'  
110°-200° byd 16 NM blo 6,000'  
121°-187° byd 40 NM  
198°-200° byd 40 NM  
260°-269° byd 40 NM  
270°-286° byd 40 NM blo 3,000'  
270°-286° byd 59 NM  
300°-302° byd 40 NM  
315°-319° byd 40 NM  
320°-330° byd 40 NM blo 4,000'  
320°-330° byd 46 NM  
325°-002° byd 31 NM blo 2,400'  
331°-335° byd 40 NM  
340°-005° byd 40 NM

